

Premier Automotive Services Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat Carros Centre, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	22/07/2023
Vehicle Reg. No.:	SMD5631X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 TURBO (A)	Vehicle Reg. Date:	27/08/2018
Vehicle Colour:	BLACK		
Engine No:	A2173268GKCX0212	Chassis No:	W0VZM6EF9J1086583
Odometer:	460790 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location:	PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ)
-------------------	--

COST OF CLAIMS

	Amount
Parts	12,776.50
Miscellaneous Items	164.00
Labour	2,680.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	15,620.50
- Excess (S\$)	2,000.00
(S\$)	13,620.50
+ GST 8.00% (S\$)	1,089.64
Nett Amount (S\$)	14,710.14

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jul 2023)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Premier Automotive Services Pte Ltd/SMD5631X/25/07/2023 11:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39214206	*FRONT BONNET <i>lt</i>	0.00	0.00	*1,705.00 F
2	1	39118540	*FRONT BONNET LOCK <i>X</i>	0.00	0.00	*43.00 F
3	1	39143307	*FRONT BONNET LOCK BRACKET <i>X</i>	0.00	0.00	*127.00 F
4	1	39126608	*FRONT BONNET HINGE LH <i>X</i>	0.00	0.00	*133.00 F
5	1	39128909	*FRONT BONNET INSULATOR <i>X</i>	0.00	0.00	*382.00 F
6	1	39107929	*FRONT RADIATOR GRILLE <i>cn</i>	0.00	0.00	*408.00 F
7	1	13491196	*FRONT RADIATOR GRILLE MOULDING (CHROME) <i>X</i>	0.00	0.00	*391.00 F
8	1	13491190	*FRONT RADIATOR GRILLE MOULDING LH (CHROME) <i>X</i>	0.00	0.00	*131.00 F
9	1	39169701	*FRONT BONNET HINGE ACTUATOR LH <i>X</i>	0.00	0.00	*309.00 F
10	1	39197502	*FRONT BUMPER UPPER INNER GARNISH <i>X</i>	0.00	0.00	*205.00 F
11	1	39114984	*FRONT RADIATOR TOP GARNISH <i>X</i>	0.00	0.00	*40.00 F
12	1	13491204	*FRONT LOGO EMBLEM <i>cn</i>	0.00	0.00	*102.00 F
13	1	39159651	*FRONT BUMPER <i>de</i>	0.00	0.00	*1,464.00 F
14	1	39098178	*FRONT BUMPER SPONGE ?	0.00	0.00	*107.00 F
15	1	39117745	*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*459.00 F
16	1	39108221	*FRONT BUMPER LOWER GRILLE <i>sun</i>	0.00	0.00	*163.00 F
17	1	13460223	*FRONT FOGLAMP LH <i>cn</i>	0.00	0.00	*253.00 F
18	1	39138751	*FRONT FOGLAMP COVER LH <i>sun</i>	0.00	0.00	*159.00 F
19	1	13491269	*INSERT, CHROME, FRONT FOGLAMP LH <i>cn</i>	0.00	0.00	*537.00 F
20	1	39020289	*FRONT BUMPER MOULDING LH <i>ms</i>	0.00	0.00	*70.00 F
21	1	39210099	*FRONT HEADLAMP LH <i>cn</i>	0.00	0.00	*1,161.00 F
22	1	13491381	*HEADLAMP BRACKET LH <i>cn</i>	0.00	0.00	*47.00 F
23	1	39077621	*FRONT UPPER SUPPORT PANEL <i>X</i>	0.00	0.00	*170.00 F
24	1	39143306	*FRONT SUPPORT PANEL <i>X</i>	0.00	0.00	*258.00 F
25	3	95515167	*FRONT PARKING SENSOR <i>ms / (1pc)</i>	0.00	0.00	*789.00 F
26	1		*FRONT BUMPER WIRING HARDNESS <i>X</i>	0.00	0.00	*323.00 F
27	1	39108782	*FRONT PEDESTRIAN CRASH SENSOR ?	0.00	0.00	*342.00 F
28	1	39125439	*FRONT FENDER LH <i>lt</i>	0.00	0.00	*597.00 F
29	1		*FRONT FENDER INNER SHIELD OUTER <i>X</i>	0.00	0.00	*120.00 F
30	1	YQ00011480	*FRONT FENDER SIGNAL LAMP COVER LH <i>X</i>	0.00	0.00	*26.00 F
31	1	13312747	*ALLOY RIM <i>X</i>	0.00	0.00	*550.00 F
32	1	YR00003380	*WIPER TANK COVER ?	0.00	0.00	*44.00 F

F=Franchise part.

Sub Total (S\$) 11,615.00
+ Margin on L,N Items 10.00% (S\$) 1,161.50

Total Parts (S\$) 12,776.50

Premier Automotive Services Pte Ltd/SMD5631X/25/07/2023 11:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	7	BUMPER CLIP <i>m /</i>	30	45.00
2	1	FRONT LICENSE PLATE WITH CASING <i>X</i>	<i>X</i>	45.00
3	10	RADIATOR TOP GARNISH CLIP SET <i>X</i>	<i>X</i>	70.00
Sub Total (\$\$)				164.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO DISMANTLE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT FENDER LH, FRONT SUPPORT PANEL, AND ETC	New	600	1,200.00
2	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION	New	30	120.00
3	TO APPLY RUST PROOFING	New	40	120.00
4	TO DISMANTLE & RENEW FRONT PARKING SENSOR & PEDESTRIAN CRASH SENSOR	New	160	120.00
5	TO CONDUCT 4 WHEEL ALIGNMENT & BALANCING	New	<i>X</i>	120.00
6	TO RESPRAY FRONT BUMPER, FRONT BONNET, FRONT FENDER LH, FRONT SUPPORT PANEL, AND ETC	New	600	1,000.00

Gross Labour Cost (\$\$) 2,680.00

Premier Automotive Services Pte Ltd/SMD5631X/25/07/2023 11:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 9000068

6 days

P/P

26/07/23

Resue by print.
excess: 2000
Reuter