

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300277
Date: 24 Jul 2023
Veh Reg No: SKP1990X
Make/Model: HONDA INSIGHT 1.3
CVT HYBRID
Chasis No: JHMZE2850ES200146
Reg. Date: 25/08/2014
Your Ref No: SKZ916R

Claim Type: Third Party
Accident Date: 17/07/2023
TP Veh Reg No: SKZ916R

Estimate Repair Cost to Vehicle No :SKP1990X

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BUMPER	881.70	
2	1 PC REAR BUMPER RETAINER - LH	41.40	
3	1 PC REAR BUMPER LOWER GARNISH	499.20	
4	1 PC REAR BUMPER REFLECTOR - LH	50.20	
5	1 PC REAR PANEL	499.60	
6	1 PC REAR PANEL TRIM	79.30	
		2,051.40	
	Less 20%	410.28	1,641.12
	Special Net		
7	1 SET REVERSE SENSORS	250.00	
8	1 SET REAR BUMPER CLIPS	60.00	
		310.00	310.00
	Labour		
9	1 TO CHECK WIRING	50.00	
10	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
11	1 (REAR) TO SPRAY PAINTING	600.00	
12	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00	
		1,330.00	1,330.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/07/2023
TP Veh Reg No: SKZ916R

Estimate No: EST2300277
Date: 24 Jul 2023
Veh Reg No: SKP1990X
Make/Model: HONDA INSIGHT 1.3
CVT HYBRID
Chasis No: JHMZE2850ES200146
Reg. Date: 25/08/2014
Your Ref No: SKZ916R

Estimate Repair Cost to Vehicle No :SKP1990X

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 3,281.12
	Add GST @ 8%		262.49
	Total Amount Payable		<u><u>S\$ 3,543.61</u></u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FIVE HUNDRED FORTY THREE AND CENTS SIXTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE