

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

Allianz Insurance Co of S'pore Pte Ltd

3 Temasek Ave

#09-01 Centennial Tower

Singapore 039190

Tel: 6297 2 Fax: 6297 1956

*Moneth*  
*96910663*

*Not Authorized*  
*1/10/23*  
*Refund After 5-6 days*

DEAR SIR / MADAM :

**ACCIDENT REPAIR ON: SLB959G**

CAR MAKE/MODEL: HONDA VEZEL

CHASSIS NO : RU11109133

DATE / TIME OF ACCIDENT: 24/06/2023 Time: 2225 AT LOR 2 TOA PAYOH

THIRD PARTY VEHICLE NO: SLU7339

Date: 25/07/2023

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

| Replacement Of Parts |                                | Unit Price | Condition | Amount     |
|----------------------|--------------------------------|------------|-----------|------------|
| S/N                  |                                | S\$        |           | S\$        |
| 1                    | TAILGATE ASSY                  | 1,252.20   |           | 1,252.20 ✓ |
| 2                    | TAILGATE WEATHERSTRIP          | 295.60     |           | 295.60 ?   |
| 3                    | TAILGATE INNER LOCK            | 395.20     |           | 395.20 ✓   |
| 4                    | TAILGATE INNER TRIMBOARD       | 315.20     |           | 315.20 ?   |
| 5                    | TAILGATE OUTER GARNISH         | 362.40     |           | 362.40 X   |
| 6                    | TAILGATE LOGO                  | 98.40      |           | 98.40 X    |
| 7                    | TAILGATE EMBLEM VEZEL          | 85.70      |           | 85.70 ✓    |
| 8                    | TAILGATE WIPER MOTOR ASSY      | 338.60     |           | 338.60 X   |
| 9                    | TAILGATE WINDSCREEN MOULDING   | 175.80     |           | 175.80 ✓   |
| 10                   | TAILGATE REFLECTOR             | 852.40     |           | 852.40 ✓   |
| 11                   | SMART BUZZER                   | 195.00     |           | 195.00 ?   |
| 12                   | TAILLAMP RH                    | 635.10     |           | 635.10 X   |
| 13                   | TAILLAMP LH                    | 635.10     |           | 635.10 ✓   |
| 14                   | REAR BUMPER                    | 785.20     |           | 785.20 ✓   |
| 15                   | REAR BUMPER SIDE RETAINER LH   | 98.00      |           | 98.00 X    |
| 16                   | REAR BUMPER SIDE RETAINER RH   | 98.00      |           | 98.00 X    |
| 17                   | REAR BUMPER REFLECTOR LH       | 125.80     |           | 125.80 X   |
| 18                   | REAR BUMPER REFLECTOR RH       | 125.80     |           | 125.80 X   |
| 19                   | REAR BUMPER CENTRE LOWER COVER | 345.80     |           | 345.80 ?   |
| 20                   | REAR END PANEL                 | 612.50     |           | 612.50 ?   |
| 21                   | REAR END PANEL TOP GARNISH     | 191.20     |           | 191.20 ?   |
| 22                   |                                |            |           |            |

Sub-Total: 8,019.00  
 Less: 20% discount - 1,603.80  
**Total Parts after 20% discount: 6,415.20**

**Special Nett Items**

|   |                           |    |        |        |          |
|---|---------------------------|----|--------|--------|----------|
| 1 | Anti-rust coating         | 1  | 80.00  | 80.00  | ?        |
| 2 | Windscreen Sealant        | 1  | 100.00 | 100.00 | 40% off  |
| 3 | End Panel Sealant         | 1  | 120.00 | 120.00 | ?        |
| 4 | Rear Bumper Sensor        | 1  | 308.00 | 308.00 | 200% off |
| 5 | Rear Bumper Clips         | 10 | 5.50   | 55.00  | —        |
| 6 | Top Garnish Clips         | 10 | 5.90   | 59.00  | ?        |
| 7 | Tailgate Inner Trim Clips | 12 | 6.70   | 80.40  | ?        |
|   |                           |    |        | 802.40 |          |

**Total Parts: 7,217.60**

**Labour Charges For Front & Rear Portion**

|                      |  |                 |     |
|----------------------|--|-----------------|-----|
| 1                    | Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. | 1,000.00        | 60% |
| 2                    | Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities             | 850.00          | 60% |
| 3                    | Remove and replace rear windscreen.  | 120.00          | ✓   |
| 4                    | Provide skill labour to remove and replace rear bumper sensor  | 80.00           | 50% |
| 5                    | Provide skill labour to disconnect and check electrical wiring   | 60.00           | 20% |
| 6                    | Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair  | 250.00          | 60% |
| <b>Total Labour:</b> |  | <b>2,360.00</b> |     |

**Total Parts & Labour: 9,577.60**  
**GST 8% 766.21**  
**Grand Total: 10,343.81**

**Estimate Repair Duration 8 days**

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,  
 ESTIMATOR: Kelvin Lim

Survey attended by:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: