



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE

GST Registration No. 201118055N Company Registration No: 201118055N

not Authorised
26/7/23
2/s < 4000/

4 days
the photo the up -

ESTIMATE

Yuen Yew Khuin
911 Tampines Street 91 #13-101 Singapore
520911

Code : C102076

Date in : 24/07/2023

Vehicle Num. : SLC9973A

Model : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Chassis/Eng# : JM6BM42A8G0339589/P520361259

Contact : 97507538

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount	
Front absorber 11	1	360.80	360.80	X
Front absorber bearing 11	1	55.80	55.80	X
Front absorber cover 11	1	36.30	36.30	X
Front absorber mounting 11	1	96.50	96.50	X
Front absorber stopper 11	1	46.40	46.40	X
Front bonnet 11	1	1120.70	1,120.70	X
Front bonnet hinges 11	2	43.10	86.20	X
Front bonnet lock 11	1	207.00	207.00	X
Front bonnet lock holder 11	1	11.40	11.40	X
Front bonnet lock protector 11	1	27.00	27.00	X
Front bonnet lock stay 11	1	34.10	34.10	X
Front bonnet parting seal weatherstrip 11	1	66.80	66.80	X
Front bonnet rubber weatherstrip (front) 11	1	27.20	27.20	X
Front bonnet rubber weatherstrip (rear) 11	1	92.00	92.00	X
Front bumper DLS	1	971.40	971.40	—
Front bumper cover 11	1	58.80	58.80	X
Front bumper reinforcement 11	1	593.40	593.40	X



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

Front bumper retainers	1/5 one	1	39.40	39.40	/
Front fender LH	Buc	1	350.60	350.60	/
Front fender outer frame LH	n	1	584.70	584.70	x
Front fender splash shield LH	To, n	1	101.90	101.90	/
Front fender stay LH	Bmf	1	41.90	41.90	/
Front fog light cover LH	groah	1	45.40	45.40	/
Front fog light LH	one	1	165.20	165.20	/
Front headlamp LH	one	1	812.00	812.00	/
Front lower arm	Bmf	1	509.00	509.00	/
Front MAZDA 'Logo' emblem	11	1	46.50	46.50	x
Front radiator grille bracket	11	1	107.60	107.60	x
Front radiator grille cover	one,	1	355.50	355.50	/
Front wheel hub with knuckle bearing	wegard	1	568.60	568.60	/
Subtotal before discount				7,620.10	
Percentage discount 10% 202				762.01	
Sub-total 1				6,858.09	
Front bumper clips (set) (sn)	neu	1	50.00	50.00	40
Front fender innershield clips (set) (sn)	neu	1	50.00	50.00	40
Front rim (sn)	n	1	550.00	550.00	x
Front tyre (sn)	11	1	280.00	280.00	x



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No. 201118055N

Subtotal before discount	930.00
Percentage discount 0%	0.00
Sub-total 2	930.00
Parts-total	7,788.09

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	120.00 20
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	150.00 80
To remove, reinstall front suspension undercarriage parts. (to FR)	450.00 120
To conduct computerise wheel alignment and adjustments	150.00 100
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,600.00 850
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,800.00 580
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	180.00 40
Labour Total	4,450.00
Parts & Labour Total	12,238.09

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 38629.0
 202
 3168.72
 80
 1790
 5038.72
 202
 4030