



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: YEE PEI LI			Ref: CS3/INC23005224/Tnp3e2-1 Date: 27/07/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 2513T	Veh. Inspected	SLJ 1362D
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1224025-002	Excess (\$)	0.00
	Assign From		Assign Date	26/07/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	GP71043538	Colour	BLACK
	Odometer	203194 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	APLUS	6 mm
	L/H Front Tyre	195/65 R15	APLUS	6 mm
	R/H Rear Tyre	195/65 R15	APLUS	6 mm
	L/H Rear Tyre	195/65 R15	APLUS	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/05/2023	Inspection Date	24/05/2023
	Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	