



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS3/MSG23007579/Tny3 Date: 26/07/2023 Code: MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		FBK 6700S	Veh. Inspected		FBU 52R
Policy No.			Coverage (\$)		0.00
Claim No.			Excess (\$)		0.00
Assign From		LEE WEE HO	Assign Date		26/07/2023
2. Vehicle Particulars & Condition					
Make & Model			c.c		0
Engine No.		HIDDEN	Year of Reg.		
Chassis No.			Colour		
Odometer		-	Steering		
Brakes			Modification		
General					
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
5. General Information					
Accident Date		24/07/2023	Inspection Date		26/07/2023
Survey held at		SG MOTORS PTE LTD 8 KAKI BUKIT AVENUE 4, #03-03, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					