

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23007584/TVY3Q2**Date:** 03/08/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP316111
Claimant Vehicle No :	SH6470U	Insured Vehicle No :	SMH3808X
Date of Loss:	25/07/2023	Nature of Claim:	TP
		Claim No:	MPC04382

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6470U		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR2C09941
Reg. Date:	02/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU603080059
Colour:	Blue	Odometer:	543714 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,909.80	1,395.93	513.87	26.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	880.00	540.00	38.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,329.80	2,275.93	1,053.87	31.65
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,329.80	1,800.00	1,529.80	45.94
+ GST 8.00/8.00% (S\$)	266.38	144.00	122.38	45.94
Nett Amount (S\$)	3,596.18	1,944.00	1,652.18	45.94

INSPECTION

Date of Assignment:	26/07/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/07/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6470U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	503.04 FL	*503.04 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	2		*REAR BUMPER RETAINER LH/RH	Not Necessary	225.40 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER TOW HOOK COVER	Deformed	82.70 FL	*82.70 FL
7	1		*TAIL GATE TOYOTA EMBLEM	Not Necessary	81.43 FL	*- FL
8	1		*TAIL GATE HYBRID EMBLEM	Necessary	62.14 FL	*62.14 FL
9	1		*TAIL GATE PRIUS EMBLEM	Necessary	62.14 FL	*62.14 FL
10	1		*REAR BUMPER ADVERTISEMENT	Cut	50.00 FS	*50.00 FS
11	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
12	1		*REAR REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
13	1		*REAR COMFORT APP STICKER	Necessary	40.00 FS	*40.00 FS
14	1		*REAR COMFORT LOGO/ TEL NO. STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,427.83	1,742.68
- List Item Discount on L Items 25.00/25.00% (S\$)	518.03	346.75
Total Parts (S\$)	1,909.80	1,395.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	60.00	0.00
Gross Labour Cost (\$\$)			1,420.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >