

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Aug 2023)
 Parts: N/A MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ricardo Auto Centre Pte Ltd/SMG9760P/01/08/2023 17:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*180.00 F	—
2	1		*FRONT BUMPER SPONGE	0.00	0.00	*38.00 F	—
3	1		*RADIATOR FILLER WITH CAP	0.00	0.00	*55.00 F	X
4	1		*RADIATOR ASSY (OEM)	0.00	0.00	*230.00 F	—
5	1		*FAN MOTOR	0.00	0.00	*300.00 F	—
6	1		*RADIATOR GRILLE INTAKE AIR	0.00	0.00	*60.00 F	—
7	1		*BONNET LOCK	0.00	0.00	*65.00 F	—
8	4		*AIR GUIDE	0.00	0.00	*80.00 F	—
9	1		*AIR CLEANER HOSE	0.00	0.00	*65.00 F	—
10	2		*FOG LAMP COVER LH & RH	0.00	0.00	*70.00 F	—
11	1		*AIR CLEANER TOP COVER	0.00	0.00	*35.00 F	—
12	1		*FRONT SUPPORT PANEL	0.00	0.00	*200.00 F	—
13	2		*HEADLAMP LH & RH	CM	0.00	*960.00 F	—
14	2		*HEADLAMP BRACKET LH & RH	0.00	0.00	*40.00 F	X SVC
15	1		*HIGH PRESSURE PIPE	0.00	0.00	*55.00 F	X SVC
16	1		*LOW PRESSURE PIPE	0.00	0.00	*55.00 F	X SVC
17	1		*AIRCON COMPRESSOR ASSY (OEM)	0.00	0.00	*450.00 F	X SVC
						Sub Total (\$\$)	2,938.00
						+ Margin on L,N Items 10.00% (\$\$)	293.80
						Total Parts (\$\$)	3,231.80

F=Franchise part.

Ricardo Auto Centre Pte Ltd/SMG9760P/01/08/2023 17:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Get no new miscellaneous items selected.

Estimates on Labour

No Particulars

Labour Items

	Lab.Type	Amount
1 TO DISMANTLE & REPLACE FRONT SUPPORT PANEL	New	500.00 ?
2 TO REMOVE & REPLACE AIRCON CONDENSER, RECHARGE AIRCON SYSTEM	New	120.00 100?
3 TO REMOVE RADIATOR ASSY & REPLACE NEW RADIATOR, TOP UP COOLANT, COOLING SYSTEM BLEEDING & PRESSURE TEST	New	180.00 50?
4 TO REMOVE & REPLACE AIRCON COMPRESSOR, HIGH & LOW PRESSURE HOSES	New	80.00 X
Gross Labour Cost (\$\$)		880.00

Ricardo Auto Centre Pte Ltd/SMG9760P/01/08/2023 17:19. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >