

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 31 Jul 2023

Preliminary Advice

Vehicle No	: SMG9760P	Accident Date	: 24/07/2023
Make	: MAZDA 5	Policy No.	: MPC23B00005202
Assignment Date	: 26/07/2023	Excess	: S\$0.00
Date of Inspection	: 31/07/2023	Est. Duration of Repair	: 4
Inspection At	: RICARDO AUTO CENTRE PTE LTD (HQ) 160 SIN MING DRIVE, #02-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,791.50
Revised Amount	:S\$	2,132.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,132.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	21,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,778.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by part basis due to no 2nd hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.