

Precise Appraiser Pte Ltd

VEHICLE DAMAGE ASSESSMENT REPORT

Reg no. 201924041Z

To: Leisure Frontier (S) Pte Ltd

CC: Connect 3

566 Woodland Road (Mandai Estate)
Singapore 728697

REFERENCES

Ref No	: 2022/03006	Date of Report	: 9/3/2022
Claim Type	: Third Party	Date of Request	: 4/3/2022
Third party vehicle	: PC8050Y	Date of Accident	: 25/2/2022
Insured Vehicle	:	Date of Inspection	: 4/3/2022
Your Reference No	: -		

DAMAGED VEHICAL PARTICULARS

Registration Plate No	: PC8050Y	Engine Modification	: NIL
Model / Make	: ISUZU LT434P	Pre-accident damage	: NIL
Colour	: Multicolor	General Condition	: Good
Manufacturing Year	: 2017	General Paint Work	: Good
Engine No	: 6HK1699331	Steering	: Serviceable
Engine Capacity	: 7800 cc	Handbrake	: Serviceable
Chassis No	: JALLT434PH7000078	Footbrake	: Serviceable
Odometer No	: 268248		
Transmission	: Auto		

TYRES CONDITION

Front Right				Rear Left x2			
Make	: Durturn			Make	: Durturn		
Size	: 295/80 r22.5	4		Size	: 295/80 r22.5	4	
Front Left				Rear Right x2			
Make	: Durturn			Make	: Durturn		
Size	: 295/80 r22.5	4		Size	: 295/80 r22.5	4	

The above millimetres represent the remaining life of tyre treads

VEHICAL REPAIR COST

<u>Descriptions</u>	<u>Repairer (\$\$)</u>	<u>Difference (\$\$)</u>	<u>Adjuster (\$\$)</u>
Parts	1,380.00		1,380.00
Labour	3,200.00		2,600.00
Calculated Cost (\$\$) :	4,580.00	600.00	3,980.00


Recommended Lump Sum Repair Cost (\$\$)	: 3,200.00
Estimate Repair Duration	: 4
Survey Inspection At	: Connect 3
Survey Inspection Address	: 566 Woodland Road (Mandai Estate) Singapore 728697

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rh Portion**.

Rear rh last compartment door dented, rh side panel dented and scatch etc.

Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **4** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inpection Report and photographs.

Handwritten signature of Anthony and the Precise Appraiser Pte Ltd logo.

Anthony
Automotive Appraiser
MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. *We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle.* All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2022/03006

Your Reference:

Vehicle Number : PC8050Y

Special Nett

S/N	Qty	Description	Condition	Repairer Estimate (S\$)	Our Assessment (S\$)
		<u>Parts</u>			
1	1pcs	Rear Rh Last Small Cover Grille	Dented	580.00	580.00
2	1pcs	Company Name Sticker	Necessary	800.00	800.00

x R
500✓

Total 1,380.00 1,380.00

<u>Labour</u>					
1		Spray Painting Multi Colors And Designs.		2,200.00	1,800.00
2		Labour Charges		1,000.00	800.00
		Labour Total		3,200.00	2,600.00
		Sub Total (labour and parts)		4,580.00	3,980.00

1500
400

Adjustment / Recommendations

Note: For Lump Sum Repair

3 days

P/P - 2400

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$3,200**.

Under normal circumstances, the repair period would be about 4 working days.