

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 04 Aug 2023

Preliminary Advice

Vehicle No	: SBN1222Y	Accident Date	: 22/07/2023
Make	: BMW 528I	Policy No.	: SP2001745076-01
Assignment Date	: 27/07/2023	Excess	: S\$600.00
Date of Inspection	: 27/07/2023	Est. Duration of Repair	: 7
Inspection At	: CAS GARAGE PTE LTD (HQ) NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,180.30
Revised Amount	:S\$	15,628.00
Check Items (Estimated)	:S\$	5,113.30
Total	:S\$	20,741.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	34,364.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,636.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer able to repair the vehicle not more than \$9,000 on lump su basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.