

SPF

TOTAL



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 26-07-2023

AUTOMOTIVE ENGG & MGNT DIV

POLICE LOGISTICS DEPARTMENT

NO:1 MOUNT PLEASANT ROAD

VEHICLE NO: SMN3141D #02-12 SINGAPORE 298333

ACCIDENT DATE : 16-07-2023 15:30

THIRD PARTY REF. : QX1836X

ATTN: SPF ACCIDENTS CLAIMS SECTION

ESTIMATE COST OF REPAIR TO VEHICLE SMN3141D BMW X1

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER LOWER	450.00 <i>cut</i>
2	1	FRONT BUMPER FOGLAMP COVER RH	188.00 <i>cut</i>
3	1	FRONT FENDER WHEEL ARCH GARNISH RH	320.00 <i>cut</i>
4	15	FRONT FENDER WHEEL ARCH GARNISH RIVET@\$.50.	82.50 ?
			1,040.50
LESS 10 %			104.05
TOTAL (A)			936.45

LABOUR CHARGES

1	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	500.00
2	1	SPRAYPAINTING CHARGES	550.00
TOTAL (D)			1,050.00
ESTIMATE TOTAL			1,986.45

Tanpin 97495749 / 62563561
 'up' 1/8/23 @ 10am
 * Resurvey new parts
 Tanpin @ 1kh auto. work
 02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is "Without Prejudice" basis
- No illegal modification
- Supplement any resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: