

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0713/2023/EQ
DATE : 29-Jul-23
WIP : 30810

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/8/2023

YOUR INSURED VEH NO : SLX 1162 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR LER ZHI KANG (LU ZHIKANG)
ADDRESS : 164 CANBERRA DRIVE
#08-55
SINGAPORE 768001
TELEPHONE : HP +65 96320109
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7220103537
VEHICLE NO : **SCQ 9780 Y**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI S-TRONIC
MODEL YEAR : 13/12/2021
ENGINE NO : CZD C43518
CHASSIS NO : WAUZZZF34M1137023
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jul-23
PLACE OF ACCIDENT : PAYA LEBAR ROAD (JUNCTION, OPP HONG LEONG CORPORATION)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCQ 9780 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
3	TO RESPRAY REAR BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	2,000.00	
4	TO REAPPLY PAINT COATING FOR THE AFFECTED AREA.	S/N	TBC	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 3,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCQ 9780 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,839.00	
2	REAR BUMPER SPOILER	1	\$ 540.00	
3	REAR BUMPER CROSS REINFORCEMENT - CENTER	1	\$ 114.00	
4	REAR BUMPER BRACKET	1	\$ 57.00	
5	REAR BUMPER REINFORCEMENT BEAM	1	\$ 736.00	
6	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 68.00	
7	REAR BUMPER SHOCK ABSORBER	1	\$ 100.00	
8	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
9	REAR PARKING AID SEAL RING	4	\$ 11.00	
10	REAR WHEEL COVER - LH / RH	2	\$ 1,200.00	
11	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 5,608.00	
TOTAL LABOUR CHARGES		:	\$ 3,752.00	
GRAND TOTAL		:	\$ 9,360.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT