



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/MSG23005910/Tqy3-1	
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807		Ref: CS3/MSG23005910/Tqy3-2	Date: 16/06/2023 28/07/2023
		Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SFY 3419D	Veh. Inspected	SMY 735C
Policy No.	1001371967	Coverage (\$)	0.00
Claim No.	316062	Excess (\$)	0.00
Assign From	CRYSTAL LEE	Assign Date	09/06/2023 28/07/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHLN41ETMU094600	Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/05/2023	Inspection Date	12/06/2023
Survey held at	Blk 3012 Bedok Industrial Park E #01-2016		
Repairer	YK SUPREME AUTOWERKZ PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			