



No . 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMP2568C

Type of Claim : TP

Vehicle No. : SMP2568C

Make & Model : BLUECAR

Year of Manufacture : 2019

Chassis No. : VL4BCEB4RKT003662

Ins Company : LONPAC INSURANCE BHD

Excess :

Date of Accident : 02/04/2023

Engine No. :

Policy No. :

Time of Accident : 00:00:00

Suggested Days of Repair : 5

Case Owner : BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : GBC1506L

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,955.00

Plus/Less— 20.0% \$ 791.00

Total of Cost / List \$ 4,746.00

(b) Nett Price Items

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 70.00

Total Parts Cost (Appendix A) \$ 4,816.00

Labour (Appendix B) \$ 2,750.00

Total Repair Cost \$ 7,566.00

The above total will be subjected to 8% G.S.T.

Name of Surveyor :

Company :

Survey conducted on : at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date:

FINALIZATION REPAIR COST DETAILS

Vehicle No	: <u>SMP2568C</u>	Case Owner	: <u>BLUECAR EAST ASIA</u> <u>PTE LTD</u>
Make & Model	: <u>BLUECAR</u>	Year Manufacture	: <u>2019</u>
Chassis No	: <u>VL4BCEB4RKT003662</u>	Engine No	: <u>0</u>
Date & Time	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER	1	\$ 2,073.00	\$ 2,073.00			
2	FRONT BUMPER CLIPS	10	\$ 2.00	\$ 20.00			
3	FRONT FENDER RH	1	\$ 1,440.00	\$ 1,440.00			
4	FRONT FENDER COVER RH	1	\$ 267.00	\$ 267.00			
5	FRONT FENDER COVER NUTS	6	\$ 1.50	\$ 9.00			
6	FRONT FENDER LAMP	1	\$ 146.00	\$ 146.00			
7	DOOR STICKER	1					\$ 70.00
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 3,929.50 \$ 3,955.00 \$ - \$ - \$ 70.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

		BLUECAR EAST ASIA	
Vehicle No.	: <u>SMP2568C</u>	Case Owner	: <u>PTE LTD</u>
Make & Model	: BLUECAR	Year of Manufacture	: 2019

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.