

ASS. REC. BY:

REF:

EGZ/230076671K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMY 8577P

Yr Regn:

03, 21

Type: M.Cat / M.Cycle / Bus / Van & Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1496

Colour

M.D. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

22799

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BP25 4AM1107076

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

27/7/23

D.O.I.

31/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) F. m/s

☐

: Tech Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

REPAIR DETAILS

Reference

Part Source: MFM-SG Version: 1.0 (Last Synchronised: 28 Jul 2023)
 Parts: 143 MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Alan's United Auto Pte Ltd/SMY8577P/28/07/2023 11:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	*650.00F
2	1		*BONNET INNER LOCK	0.00	0.00	*140.00F
3	1		*BONNET INNER LOCK BRACKET	0.00	0.00	*24.00F
4	1		*BONNET FRONT RUBBER	0.00	0.00	*45.00F
5	2		*BONNET HINGE	0.00	0.00	*112.00F
6	1		*FRONT BUMPER TOP	0.00	0.00	*380.00F
7	10		*FRONT BUMPER TOP RIVET (BLACK)	0.00	0.00	*45.00F
8	8		*FRONT BUMPER TOP CLIP (SMALL)	0.00	0.00	*30.40F
9	4		*FRONT BUMPER TOP CLIP SIDE (BIG)	0.00	0.00	*18.00F
10	1		*FRONT BUMPER TOP BEAM	0.00	0.00	*155.00F
11	1		*FRONT BUMPER LOWER	0.00	0.00	*580.00F
12	2		*FRONT BUMPER CENTRE CHROME	0.00	0.00	*380.00F
13	2		*FRONT BUMPER CENTRE CHROME SIDE INNER GARNISH	0.00	0.00	*60.00F
14	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*370.00F
15	1		*FRONT BUMPER REINFORCEMENT CENTRE GUIDE	0.00	0.00	*150.00F
16	2		*FRONT BUMPER REINFORCEMENT TOP GUIDE	0.00	0.00	*22.00F
17	1		*FRONT BUMPER LICENSE PLATE GARNISH	0.00	0.00	*60.00F
18	1		*FRONT RH BUMPER SIDE RETAINER	0.00	0.00	*20.00F
19	1		*FRONT GRILLE	0.00	0.00	*170.00F
20	2		*FRONT GRILLE TOP SIDE BRACKET	0.00	0.00	*32.00F
21	1		*FRONT GRILLE LOGO WITH CAMERA	0.00	0.00	*600.00F
22	1		*FRONT GRILLE LOGO HOLDER	0.00	0.00	*40.00F
23	1		*FRONT GRILLE CAMERA MONITOR	0.00	0.00	*780.00F
24	2		*HEADLAMP	0.00	0.00	*5,600.00F
25	2		*HEADLAMP LOWER BRACKET	0.00	0.00	*100.00F
26	1		*FRONT SUPPORT TOP PANEL	0.00	0.00	*150.00F
27	1		*FRONT CENTRE SUPPORT PANEL	0.00	0.00	*310.00F
28	1		*FRONT CENTRE SUPPORT PANEL BRACKET	0.00	0.00	*45.00F
29	1		*FRONT NO. PLATE WITH BOX	0.00	0.00	*50.00FS
30	1		*RADIATOR COOLANT	0.00	0.00	*30.00FS

Sub Total (S\$) 11,148.40

+ Margin on L,N Items 10.00% (S\$) 1,106.84

Total Parts (S\$) 12,255.24

LKK Auto Consultants hence notify the Repairer of the following:

Alan's United Auto Pte Ltd/SMY8577P/28/07/2023 11:46. Not valid without Reference section.

- To display damaged part(s) during General
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP,DAGNOSTIC & RESET HEADLAMP SYSTEM	New	200.00 7
2	TO DIAGNOSTIC AND RESET CAMERA SYSTEM	New	180.00 7
3	TO REMOVE AIR CON CONDENSER,PIPES & DRIER,VACUUM AND TO RECHARGE GAS	New	100 120.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	600 800.00
5	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	600 800.00
Gross Labour Cost (\$\$)			2,100.00

Alan's United Auto Pte Ltd/SMY8577P/28/07/2023 11:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	023159
Policy No:	DMPG23003847	Date of Loss:	27/07/2023
Vehicle Reg. No.:	SMY8577P	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOW CHANG LIAN	Contact No:	+6597920538
Driver:	CHOW CHANG LIAN		

Make/Model:	MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A)	Vehicle Reg. Date:	29/03/2021
Vehicle Colour:	BLUE	Chassis No:	JM6BP25AAM1107076
Engine No:	P520726486		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)		

Not Notified
Repair B&Pain
Ex TBA

5day

COST OF CLAIMS

	Amount
Parts	12,255.24
Miscellaneous Items	0.00
Labour	2,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	14,355.24
+ GST 8.00% (S\$)	1,148.42
Nett Amount (S\$)	15,503.66

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 786C

Vehicle Details

Vehicle No.: SMY8577P
Vehicle to be Exported: Yes
Intended Deregistration Date: 31 Jul 2023
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4DR 1.5 AT M-HYBRID ELEGANCE
Primary Colour: Blue
Manufacturing Year: 2021
Engine No.: P520726486
Chassis No.: JM6BP2SAAM1107076
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$23,417.00
Original Registration Date: 29 Mar 2021
First Registration Date: 29 Mar 2021
Transfer Count: 0
Actual ARF Paid: \$9,784.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Mar 2031
PARF Rebate Amount: \$7,338.00

Intended COE Rebate Details

COE Expiry Date: 28 Mar 2031
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$44,589.00
COE Rebate Amount: \$34,148.00
Total Rebate Amount: \$41,486.00

The information contained herein is correct as at 31 Jul 2023

OK