



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | CS3/III22007072/Dcy3-1 | |
|--|--|------|--|----------------------------------|--|
| INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | | Ref: CS3/III22007072/Vcy3 Date: 25/07/2022 28/07/2023 Code: III2 | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| Insured Veh. | GBH 8173R | | Veh. Inspected | SMS 7124B | |
| Policy No. | | | Coverage (\$) | 0.00 | |
| Claim No. | | | Excess (\$) | 0.00 | |
| Assign From | BHUVANESWARI | | Assign Date | 25/07/2022 28/07/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| Make & Model | | | c.c | 0 | |
| Engine No. | HIDDEN | | Year of Reg. | | |
| Chassis No. | | | Colour | | |
| Odometer | - | | Steering | | |
| Brakes | | | Modification | | |
| General | | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| R/H Front Tyre | | | | mm | |
| L/H Front Tyre | | | | mm | |
| R/H Rear Tyre | | | | mm | |
| L/H Rear Tyre | | | | mm | |
| 4. Description of Damages | | | | | |
| | | | | | |
| 5. General Information | | | | | |
| Accident Date | 22/07/2022 | | Inspection Date | 26/07/2022 | |
| Survey held at | GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. | | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |