

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Steve Lim

Date: 01 Aug 2023

Preliminary Advice

Vehicle No	: SNB6080C	Accident Date	: 20/07/2023
Make	: TOYOTA LEXUS	Policy No.	: SP2004972550-01
Assignment Date	: 29/07/2023	Excess	: S\$600.00
Date of Inspection	: 31/07/2023	Est. Duration of Repair	: 12
Inspection At	: ELITE AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,490.00
Revised Amount	:S\$	13,400.00
Check Items (Estimated)	:S\$	18,125.00
Total	:S\$	31,525.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	25,036.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,964.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
- Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.