

Elite Automotive Pte Ltd (Co.Reg.No:201700196D)

280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands

Singapore 757322

Tel: 9388 2885/8136 4741/63397378 Fax: 63397475 Email: elite.automotive13@gmail.com

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: SP2004972550-01
Vehicle Reg. No.: SNB6080C
Driver Age/Info: 46 / MALE
TP Injury Involved? NO
Insured/Claimant: TIN KEK LEONG ALVIN
Driver: TIN KEK LEONG ALVIN

Ref. No:
Date of Loss: 20/07/2023
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES
Contact No: +6587780608

Make/Model: TOYOTA LEXUS, 2.5 IS250 (A)
Vehicle Colour: WHITE
Engine No: 4GR0692773
Odometer: 179586 KM

Vehicle Reg. Date: 22/09/2010
Chassis No: JTHBK262802100695

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 14

Description of Accident/Loss: PLEASE REFER TO
Present Location: ELITE AUTOMOTIVE PTE LTD (HQ)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COST OF CLAIMS

	Amount
Parts	42,190.00
Miscellaneous Items	80.00
Labour	7,220.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$) 49,490.00

- Excess (S\$) 600.00

(S\$) 48,890.00

+ GST 8.00% (S\$) 3,911.20

Nett Amount (S\$) 52,801.20

This claim is handled by: HANG PEK CHIN

Tanfilm 97495749/62563561

Not Authorise Ex 9600

4/7/23 @ 1230 pm

Tanfilm e/hand.com

10-12 days

To check to repair L/S on p/p
Resurvey before/after paint.

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jul 2023)
 Parts: 143 TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SNB6080C)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	Ry *1,900.00 F
2	1		*BONNET LOCK	0.00	0.00	X *150.00 F
3	1		*BONNET INSULATION	0.00	0.00	X *260.00 F
4	15		*BONNET INSULATION CLIPS	0.00	0.00	X *45.00 F
5	2		*BONNET HINGES (LH & RH)	0.00	0.00	X *240.00 F
6	1		*FRONT GRILLE	0.00	0.00	char *670.00 F
7	10		*FRONT GRILLE CLIPS	0.00	0.00	char *30.00 F
8	1		*FRONT GRILLE LOGO	0.00	0.00	mis *120.00 F
9	1		*FRONT BUMPER	0.00	0.00	fn *1,100.00 F
10	10		*FRONT BUMPER CLIPS	0.00	0.00	ng *30.00 F
11	2		*FRONT BUMPER RETAINER (LH & RH)	0.00	0.00	? *240.00 F
12	2		*FRONT BUMPER SIDE GRILLE (LH & RH)	0.00	0.00	? *220.00 F
13	1		*FRONT BUMPER INNER SPONGE	0.00	0.00	mis *90.00 F
14	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	X *380.00 F
15	2		*DAYLIGHT (LH & RH)	0.00	0.00	*700.00 F
16	2		*HEADLAMP (LH & RH)	0.00	0.00	? *3,100.00 F
17	2		*HEADLAMP LOWER BRACKET (LH & RH)	0.00	0.00	? *240.00 F
18	2		*FRONT SPLASH SHIELD (LH & RH)	0.00	0.00	de *560.00 F
19	20		*FRONT SPLASH SHIELD CLIPS	0.00	0.00	40 ag *60.00 F
20	2		*FRONT FENDER (LH & RH)	RHX 0.00	0.00	LH *1,800.00 F
21	1		*SUPPORT PANEL	0.00	0.00	X *700.00 F
22	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	X *260.00 F
23	10		*SUPPORT PANEL TOP GARNISH CLIPS	0.00	0.00	X *30.00 F
24	2		*FRONT SHOCK ABSORBER (LH & RH)	LHX 0.00	0.00	LH *1,300.00 F
25	2		*FRONT SHOCK ABSORBER STOPPER (LH & RH)	RHX 0.00	0.00	LH *240.00 F
26	2		*FRONT LOWER ARM (LH & RH)	RHX 0.00	0.00	LH *600.00 F
27	2		*FRONT KNUCKLE ARM (LH & RH)	RHX 0.00	0.00	LH *640.00 F
28	2		*FRONT KNUCKLE BEARING (LH & RH)	RHX 0.00	0.00	LH *760.00 F
29	2		*FRONT STABILIZER LINK (LH & RH)	RHX 0.00	0.00	LH *160.00 F
30	1		*FRONT CROSSMEMBER	0.00	0.00	? *850.00 F
31	2		*FRONT RIM (LH & RH)	RHX 0.00	0.00	LH *2,400.00 F
32	2		*FRONT TYRE (LH & RH)	RHX 0.00	0.00	LH *1,100.00 F
33	1		*FRONT LHS DOOR	0.00	0.00	bt *720.00 F
34	1		*FRONT LHS DOOR WEATHERSTRIP	0.00	0.00	? *180.00 F
35	1		*FRONT LHS DOOR INNER TRIM	0.00	0.00	? *1,600.00 F
36	2		*FRONT LHS DOOR HINGES	0.00	0.00	X *160.00 F
37	1		*FRONT LHS DOOR LOCK	0.00	0.00	X *480.00 F
38	1		*FRONT LHS DOOR POWER WINDOW MOTOR	0.00	0.00	? *800.00 F
39	1		*FRONT LHS DOOR REGULATOR	0.00	0.00	? *250.00 F
40	1		*FRONT LHS DOOR HANDLE	0.00	0.00	X *350.00 F
41	1		*REAR LHS DOOR INNER TRIM	0.00	0.00	? *1,600.00 F
42	15		*REAR LHS DOOR INNER TRIM CLIPS	0.00	0.00	? *45.00 F
43	1		*REAR LHS DOOR POWER WINDOW MOTOR	0.00	0.00	? *750.00 F
44	1		*REAR LHS DOOR REGULATOR	0.00	0.00	? *520.00 F
45	1		*REAR LHS DOOR WEATHERSTRIP	0.00	0.00	? *340.00 F

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*LHS SIDE SKIRT			
47	2		*REAR FENDER (LH & RH)	RHX 0.00	0.00 cur ✓	*440.00 F
48	2		*REAR RIM (LH & RH)	0.00	0.00 LH ✓	*1,500.00 F
49	2		*REAR TYRE (LH & RH)	RHX 0.00	0.00 LH ✓	*2,400.00 F
50	2		*REAR SHOCK ABSORBER (LH & RH)	RHX 0.00	0.00 LH ✓	*1,100.00 F <i>parted</i>
51	2		*REAR SHOCK ABSORBER STOPPER	RHX 0.00	0.00 LH ?	*1,500.00 F
52	2		*REAR KNUCKLE ARM (LH & RH)	RHX 0.00	0.00 LH ?	*240.00 F
53	2		*REAR KNUCKLE BEARING (LH & RH)	RHX 0.00	0.00 LH ?	*1,300.00 F
54	2		*REAR LOWER ARM (LH & RH)	RHX ? 0.00	0.00 LH ?	*1,160.00 F
55	2		*REAR STABILIZER LINK	RHX ? 0.00	0.00 LH ?	*500.00 F
56	1		*REAR BUMPER	0.00	0.00 ?	*480.00 F
57	10		*REAR BUMPER CLIPS	0.00	0.00 di ✓	*750.00 F
58	2		*REAR BUMPER RETAINER (LH & RH)	0.00	0.00 di ✓	*30.00 F
59	1		*REAR BUMPER REINFORCEMENT	RHX 0.00	0.00 LH ?	*160.00 F
60	1		*REAR BUMPER INNER SPONGE	0.00	0.00 X	*360.00 F
61	2		*REAR BUMPER SIDE GRILLE (LH & RH)	0.00	0.00 X	*130.00 F
62	1		*TOWING CAP	0.00	0.00 X	*240.00 F
63	2		*REAR SPLASH SHIELD (LH & RH)	0.00	0.00 X	*50.00 F
64	20		*REAR SPLASH SHIELD CLIPS	RHX 0.00	0.00 LH ✓	*420.00 F
65	1		*RHS SIDE SKIRT	0.00	0.00 cur ✓	*60.00 F <i>30</i>
66	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00 X	*440.00 F
				0.00	0.00 X	*160.00 F

F=Franchise part.

Total Parts (S\$)

42,190.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT NUMBER PLATE WITH HOLDER	80.00
Sub Total (\$\$)			X 80.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	LABOUR CHARGES TO REMOVE DAMAGED PARTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	New	1500	2,800.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1800	2,200.00
3	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS; TO VACUUM & CHARGE UP GAS	New	X ?	150.00
4	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIRS, INCLUDING PRESSURIZE COOLING SYSTEM.	New	X ?	150.00
5	TO REMOVE & INSTALL FRONT & REAR UNDERCARRIAGE.	New	300? plus	800.00
6	WHEEL ALIGNMENT	New	80	120.00
7	TO CHECK & REALIGNMENT ON CHASSIS MEMBER.	New	X	600.00
8	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	New	50	200.00
9	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	New	X	200.00

Gross Labour Cost (\$\$) 7,220.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	390J

Vehicle Details

Vehicle No.:	SNB6080C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	4GR0692773
Chassis No.:	JTHBK262802100695
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$38,845.00
Original Registration Date:	22 Sep 2010
First Registration Date:	22 Sep 2010
Transfer Count:	4
Actual ARF Paid:	\$38,845.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	21 Sep 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$34,935.00
COE Rebate Amount:	\$25,036.00
Total Rebate Amount:	\$25,036.00

The information contained herein is correct as at 21 Jul 2023

OK