

M-TECH MOTOR SERVICES

Block 9005, Tampines St. 93 #01-252, Tampines Industrial Park A, Singapore 528839
Tel: 784 0077 Fax: 788 3025

not approved
see

Date: 28 July 2023

31/7/23
L/S # 3400

3 days
take back after repair

ESTIMATED REPAIR COST OF VEHICLE NO. SMR 6008 R MERCEDES BENZ C180

Nett List Items

2	Rear taillamps	<i>11 X</i>		\$	1,670.00	X
1	Rear end panel	<i>R</i>		\$	1,248.00	X
1	Rear end panel inner garnish	<i>11</i>		\$	165.00	X
1	Rear bumper	<i>12/22</i>	<i>1890.15</i>	\$	2,085.00	✓
2	Rear bumper brackets	<i>201</i>		\$	172.00	✓
1	Rear bumper inner sponge	<i>NS</i>		\$	162.00	✓
1	Rear bumper lower chrome moulding	<i>SCR</i>	<i>255.00</i>	\$	480.00	✓
1	Rear bumper reinforcement	<i>R</i>		\$	817.00	X
2	Rear bumper side retainers	<i>11 X</i>		\$	170.00	X
1	Rear bumper lower diffuser	<i>322.6</i>	<i>381.40</i>	\$	1,280.00	✓
4	Rear bumper PDC sensors	<i>modification</i>	<i>182.70 x 2 = 365.40</i>	\$	1,540.00	<i>270</i>
1	Rear bumper inner frame pad	<i>101</i>	<i>188.60</i>	\$	285.00	✓
1	Control module for park assistant kit	<i>17</i>		\$	345.00	X
				\$	10,419.00	
				<i>(10% Less 5%)</i>	\$	520.95
				\$	9,898.05	

Special Nett Items

1	Rear bumper clip (1 set)	<i>net</i>		\$	80.00	<i>50</i>
				\$	80.00	

S/N Labour Cost

1	To remove, replaced damaged lamps and check up rear wiring.			\$	80.00	<i>20</i>
2	To remove and refit inner garnishes.			\$	180.00	<i>60</i>
3	To remove and refit rear reverse sensor.			\$	150.00	<i>50</i>
4	To apply undercoating.			\$	150.00	<i>X</i>
5	Panel beating.			\$	1,400.00	<i>550</i>
6	To re-spray painting on the affected areas.			\$	1,200.00	<i>600</i>
				\$	3,160.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total \$ 13,138.05

1-3253.38
102
2928.02

Acknowledged by Repairer
Signature:
Date: