

ZENITH AUTOMOTIVE SERVICES

BLK 1010 BUKIT MERAH LANE 3

#01-121 SINGAPORE 159724

Tel No. : 62782017 / 62782018 Fax No. : 62719523

E-Mail : zenith77@singnet.com.sg

Tax Reg. No. : 37-214300-L Buss. Reg. No. : 37-214300-L

Estimate : 00000773

ALLIANZ INSURANCE COMPANY OF SINGAPORE P.LTD

3, TEMASEK AVE.

#03-01, CENTENNIAL TOWER, S'PORE 039190

Attention : Motor Claim Department

Contact : 63953857/63953848 A 62972529 Fax No. : 63953768

Date : 31/07/2023

Vehicle No : SW 3333 Z

Make/Model : MER GLB 200

Chassis No :

Acc. Date : 28/07/2023

Claim No :

Reference :

Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.		FRONT BUMPER <i>de</i>		1,147.00
2.		FRONT BUMPER GARNISH (LH) <i>sun</i>		114.00
3.		FRONT BUMPER GARNISH (RH) <i>sun</i>		114.00
4.		FRONT BUMPER GRILLE <i>com</i>		754.00
5.		FRONT GRILLE EMBLEM <i>com</i>		127.00
6.		GRILLE EMBLEM HOLDER <i>com</i>		314.00
7.		GRILLE SENSOR HOLDER <i>sun</i>		25.00
8.		GRILLE SENSOR <i>sun</i>		120.00
9.		RADAR MODULE ?		640.00
10.		MODULE HOLDER <i>de</i>		54.00
11.	2 PCS	BONNET PLUNGER <i>act</i>	200.00	400.00
12.	2 PCS	BONNET HINGE ?	138.00	276.00
Total Parts Purchased S\$:				4,065.00
15.00% OT The Above Parts S\$:				612.75
Based On Cost Plus S\$:				4,697.75
NETT ITEMS :				
1.		FRONT NO. PLATE <i>bf</i>		70.00
Nett Total S\$:				70.00
LABOUR :				
TO REPSRAY FRONT BUMPER.			300 250	480.00
TO REMOVE & REPLACE ALL DAMAGED BODY PARTS			300	550.00
TO REMOVE & REPLACE FRONT RADAR & HOLDER, CARRY OUT			800	950.00

CONTINUE / ...

ZENITH AUTOMOTIVE SERVICES

BLK 1010 BUKIT MERAH LANE 3

#01-121 SINGAPORE 159724

Tel No. : 62782017 / 62782018 Fax No. : 62719523

E-Mail : zenith77@singnet.com.sg

Tax Reg. No. : 37-214300-L Buss. Reg. No. : 37-214300-L

Estimate : 00000773

ALLIANZ INSURANCE COMPANY OF SINGAPORE P.LTD

3, TEMASEK AVE.

#03 - 01, CENTENNIAL TOWER, S'PORE 039190

Attention : Motor Claim Department

Contact : 63953857/63953848 A 62972529 Fax No. : 63953768

Date : 31/07/2023

Vehicle No : SW 3333 Z

Make/Model : MER GLB 200

Chassis No :

Acc. Date : 28/07/2023

Claim No :

Reference :

Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PROGRAMMING & CALIBRATIONS.

Labour Total S\$.

1,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
4p 90010068
4 days
P/P
01/08/23
EXCESS: 600
REPAIR
Resy by paint

Total S\$.

6,747.75

FOR ZENITH AUTOMOTIVE SERVICES

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun.