



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0716/2023/EQ  
**DATE** : 31-Jul-23  
**WIP** : 30974

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/8/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR LIM BAK CHIM  
**ADDRESS** : 20 CHOA CHU KANG STREET 64  
#14-02  
SINGAPORE 689093  
**TELEPHONE** : HP +65 91387770  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1800022296-05  
**VEHICLE NO** : **SJW 8190 S**  
**MODEL CODE** : AUDI A3 SEDAN 1.0 TFSI  
**MODEL YEAR** : 8/3/2018  
**ENGINE NO** : CHZ 653023  
**CHASSIS NO** : WAUZZZ8V6J1046233  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 28-Jul-23  
**PLACE OF ACCIDENT** : SINGPOST MALL B1 CARPARK, ACCIDENT HAPPEN IN THE CARPARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 8190 S**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,000.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 7,670.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 8190 S**

<b>S/N</b>	<b>NATURE OF JOBS</b>		<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$	5,000.00	
8	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME.	S/N \$	2,800.00	
9	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 16,374.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	FRONT BUMPER	1	\$ 2,576.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 207.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 606.00	
5	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 337.00	
6	FRONT BUMPER TRIM COVER - LH	1	\$ 193.00	
7	FRONT WHEEL HOUSING LINER ADAPTER - LH	1	\$ 45.00	
8	RADIATOR GRILLE	1	\$ 1,679.00	
9	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 223.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 222.00	
11	AIR CONDITIONER STICKER	1	\$ 9.00	
12	CAUTION SIGN STICKER	1	\$ 17.00	
13	HORN HIGH TONE - LH	1	\$ 225.00	
14	FRONT FENDER - LH	1	\$ 1,012.00	
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 80.00	
16	FRONT FENDER BRACKET - LH CENTER	1	\$ 57.00	
17	FRONT FENDER RIVET	6	\$ 24.00	
18	FRONT FENDER BRACKET - LH REAR	1	\$ 34.00	
19	FRONT FENDER BRACE	1	\$ 114.00	
20	FRONT FENDER INSULATION - LH	1	\$ 51.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 7,757.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
21	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 39.00	
22	FRONT WHEEL HOUSING LINER SEAL - LH	1	\$ 41.00	
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 198.00	
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 99.00	
25	BONNET	1	\$ 3,412.00	
26	BONNET EDGE PROTECTION	1	\$ 33.00	
27	BONNET SIDE SEAL - LH	1	\$ 51.00	
28	HEADLIGHT - LH	1	\$ 6,232.00	
29	HEADLIGHT POWER MODULE - LH	1	\$ 876.00	
30	HEADLIGHT CONTROL UNIT	1	\$ 643.00	
31	HEADLIGHT HEAT SINK -LH	1	\$ 868.00	
32	HEADLIGHT HOSE - LH	1	\$ 99.00	
33	LIFT CYLINDER - LH	1	\$ 165.00	
34	LIFT CYLINDER HOSE	1	\$ 81.00	
35	LIFT CYLINDER WASH WATER RESERVOIR	1	\$ 231.00	
36	LOCK CARRIER	1	\$ 854.00	
37	READY-MIX COOLANT	6	\$ 326.00	
38	RADIATOR AIR GUIDE - LH	1	\$ 31.00	
39	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 20.00	
40	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH	1	\$ 366.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 14,665.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
41	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH	1	\$ 304.00	
42	FRONT WATER DEFLECTOR STRIP - LH	1	\$ 110.00	
43	FRONT PLENUM CHAMBER COVER	1	\$ 211.00	
44	FRONT ASSEMBLY CARRIER	1	\$ 1,228.00	
45	1 SET BONDED RUBBER BUSHES	1	\$ 117.00	
46	FRONT CONTROL ARM - LH LOWER	1	\$ 396.00	
47	FRONT STABILIZER	1	\$ 470.00	
48	FRONT WHEEL BEARING HOUSING	1	\$ 642.00	
49	FRONT WHEELHUB WITH BEARING	1	\$ 554.00	
50	FRONT GUIDE JOINT	1	\$ 138.00	
51	FRONT COUPLING ROD	1	\$ 105.00	
52	FRONT DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS - LH	1	\$ 1,548.00	
53	FRONT GAS SHOCK ABSORBER	1	\$ 291.00	
54	FRONT STEERING GEAR	1	\$ 5,750.00	
55	FRONT TRACK ROD	1	\$ 107.00	
56	FRONT TIE ROD END - LH	1	\$ 132.00	
57	FRONT NUMBER PLATE	S/N	\$ 60.00	
58	LHS FRONT RIM	S/N	TBC	
59	LHS FRONT TYRE	S/N	TBC	
60	SUNDRIES		\$ 1,000.00	
<b>TOTAL SPARE PARTS</b>			<b>: \$ 35,585.00</b>	
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 16,374.00</b>	
<b>GRAND TOTAL</b>			<b>: \$ 51,959.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT