

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0716/2023/EQ
DATE : 31-Jul-23
WIP : 30974

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/8/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM BAK CHIM
ADDRESS : 20 CHOA CHU KANG STREET 64
#14-02
SINGAPORE 689093
TELEPHONE : HP +65 91387770
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800022296-05
VEHICLE NO : **SJW 8190 S**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 8/3/2018
ENGINE NO : CHZ 653023
CHASSIS NO : WAUZZZ8V6J1046233
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jul-23
PLACE OF ACCIDENT : SINGPOST MALL B1 CARPARK, ACCIDENT HAPPEN IN THE CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 8190 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$	280.00	X
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	/
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	/
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	?
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,000.00	1500
TOTAL LABOUR CHARGES		:	\$	7,670.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 8190 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$ 5,000.00	1650
8	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME.	S/N \$ 2,800.00	?
9	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	/
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 16,374.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	1	\$ 2,576.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 207.00	
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 46.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 606.00	
5	FRONT BUMPER CLOSING ELEMENT - LH <i>?</i>	1	\$ 337.00	
6	FRONT BUMPER TRIM COVER - LH <i>X</i>	1	\$ 193.00	
7	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>?</i>	1	\$ 45.00	
8	RADIATOR GRILLE <i>CR</i>	1	\$ 1,679.00	
9	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 223.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	1	\$ 222.00	
11	AIR CONDITIONER STICKER <i>m</i>	1	\$ 9.00	
12	CAUTION SIGN STICKER <i>m</i>	1	\$ 17.00	
13	HORN HIGH TONE - LH <i>?</i>	1	\$ 225.00	
14	FRONT FENDER - LH <i>bu</i>	1	\$ 1,012.00	
15	FRONT FENDER ATTACHMENT PARTS <i>X</i>	1	\$ 80.00	
16	FRONT FENDER BRACKET - LH CENTER <i>H</i>	1	\$ 57.00	
17	FRONT FENDER RIVET <i>m</i>	6	\$ 24.00	
18	FRONT FENDER BRACKET - LH REAR <i>m</i>	1	\$ 34.00	
19	FRONT FENDER BRACE <i>?</i>	1	\$ 114.00	
20	FRONT FENDER INSULATION - LH <i>?</i>	1	\$ 51.00	
SUB TOTAL SPARE PARTS			\$ 7,757.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6396 2323 FAX: 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$ 39.00	
22	FRONT WHEEL HOUSING LINER SEAL - LH ?	1	\$ 41.00	
23	FRONT WHEEL HOUSING LINER - LH de/	1	\$ 198.00	
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS m/	1	\$ 99.00	
25	BONNET cap LH-	1	\$ 3,412.00	
26	BONNET EDGE PROTECTION m/	1	\$ 33.00	
27	BONNET SIDE SEAL - LH m/	1	\$ 51.00	
28	HEADLIGHT - LH l/	1	\$ 6,232.00	
29	HEADLIGHT POWER MODULE - LH ?	1	\$ 876.00	
30	HEADLIGHT CONTROL UNIT ?	1	\$ 643.00	
31	HEADLIGHT HEAT SINK - LH ?	1	\$ 868.00	
32	HEADLIGHT HOSE - LH ?	1	\$ 99.00	
33	LIFT CYLINDER - LH ?	1	\$ 165.00	
34	LIFT CYLINDER HOSE ?	1	\$ 81.00	
35	LIFT CYLINDER WASH WATER RESERVOIR ?	1	\$ 231.00	
36	LOCK CARRIER ?	1	\$ 854.00	
37	READY-MIX COOLANT ?	6	\$ 326.00	
38	RADIATOR AIR GUIDE - LH ?	1	\$ 31.00	
39	RADIATOR AIR GUIDE - UPPER CENTRE ?	1	\$ 20.00	
40	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH X	1	\$ 366.00	
SUB TOTAL SPARE PARTS			\$ 14,665.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 8190 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH X	1	\$	304.00	
42	FRONT WATER DEFLECTOR STRIP - LH at ✓	1	\$	110.00	
43	FRONT PLENUM CHAMBER COVER X	1	\$	211.00	
44	FRONT ASSEMBLY CARRIER ?	1	\$	1,228.00	
45	1 SET BONDED RUBBER BUSHES ?	1	\$	117.00	
46	FRONT CONTROL ARM - LH LOWER ?	1	\$	396.00	
47	FRONT STABILIZER ?	1	\$	470.00	
48	FRONT WHEEL BEARING HOUSING ?	1	\$	642.00	
49	FRONT WHEELHUB WITH BEARING ?	1	\$	554.00	
50	FRONT GUIDE JOINT ?	1	\$	138.00	
51	FRONT COUPLING ROD ?	1	\$	105.00	
52	FRONT DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS ? - LH	1	\$	1,548.00	
53	FRONT GAS SHOCK ABSORBER ?	1	\$	291.00	
54	FRONT STEERING GEAR ?	1	\$	5,750.00	
55	FRONT TRACK ROD ?	1	\$	107.00	
56	FRONT TIE ROD END - LH ?	1	\$	132.00	
57	FRONT NUMBER PLATE her ✓	S/N	\$	60.00	
58	LHS FRONT RIM see ✓	S/N		TBC	
59	LHS FRONT TYRE X	S/N		TBC	
60	SUNDRIES ?		\$	1,000.00	
TOTAL SPARE PARTS		:	\$	35,585.00	
TOTAL LABOUR CHARGES		:	\$	16,374.00	
GRAND TOTAL		:	\$	51,959.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6368 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Rasul - 4 90010068
SURVEYED DATE : 02/08/23 @ 1415
AUTHORISED DATE :
EXCESS COST : 6 days
LIABILITY :
REMARKS : EXCESS: TBA
REPAIR
Respray LF part

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY FOR INSPECTION OF VEHICLE. PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	949A
Vehicle No.:	SJW81905
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2023
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CHZ653023
Chassis No.:	WAUZZZ8V6J1046233
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,701.00
Original Registration Date:	08 Mar 2018
First Registration Date:	08 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$26,582.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Mar 2028
PARF Rebate Amount:	\$18,607.00
COE Expiry Date:	07 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$16,957.00
Total Rebate Amount:	\$35,564.00

The information contained herein is correct as at 02 Aug 2023

OK

Audi A3 Sportback 1.0A TFSI S-tronic

\$81,800 Instalment \$1,203/mth

Apply for 2.28% loan

Shortlist

Get Warranty

 **KONNICHIWA! TOKYO AWAITS!**  One-way from **\$240*** [Book now](#) 

Overview Financial Photo Research

Depreciation	 \$15,270 / year
Reg. Date	05-Feb-2018 (4yrs 6mths 2days COE left)
Manufactured	 2017
Mileage	58,938 km (10.7k / year)
Transmission	Auto
Engine Cap	999 cc
Road Tax	 \$392 / year
Power	85.0 kW (113 bhp) View specs of the Audi A3 Sportback (2013-2020)
Curb Weight	 1,275 kg
COE	 \$36,890
OMV	 \$24,162
ARF	 \$25,827
Dereg Value	 \$34,725 as of today
No. of Owners	 2