

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0726/2023/EQ
DATE : 1-Aug-23
WIP : 31360

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/8/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE ROAD
SINGAPORE 159090

TELEPHONE : HP +65 91156516
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SMA 1237 T**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 28/5/2018
ENGINE NO : CVK 058480
CHASSIS NO : WAUZZZF54JA086555
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jul-23
PLACE OF ACCIDENT : PRINCE GEORGE'S PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1237 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	
TOTAL LABOUR CHARGES		:	\$ 4,660.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1237 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	
8	TO RESPRAY REAR BUMPER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL TRIM, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$	7,500.00	
9	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 20,072.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1237 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,187.00	
2	REAR BUMPER FIXING PARTS	1	\$ 289.00	
3	REAR BUMPER SECURING STRIP	1	\$ 264.00	
4	REAR BUMPER CHROME TRIM	1	\$ 1,206.00	
5	REAR BUMPER GUIDE SECTION - LH UPPER	1	\$ 27.00	
6	REAR BUMPER GUIDE SECTION - LH	1	\$ 52.00	
7	REAR SIDE PANEL - LH	1	\$ 4,315.00	
8	REAR QUARTER WINDOW - LH	1	\$ 844.00	
9	WINDOW PRIMER	1	\$ 24.00	
10	REAR WHEEL HOUSING LINER - LH	1	\$ 322.00	
11	ATTACHMENT PARTS	1	\$ 144.00	
12	ADHESIVE TAPES	1	\$ 230.00	
13	REAR DOOR - LH	1	\$ 4,210.00	
14	REAR DOOR OUTER SEAL - LH	1	\$ 261.00	
15	BONDING AGENT	1	\$ 51.00	
16	CLEANING SOLUTION	1	\$ 80.00	
17	APPLICATOR	1	\$ 9.00	
18	REAR DOOR CATCH - LH	1	\$ 141.00	
19	REAR DOOR ATTACHMENT PARTS	1	\$ 141.00	
20	REAR ALUMINIUM RIM - LH	1	\$ 2,000.00	
SUB TOTAL SPARE PARTS		:	\$ 17,797.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1237 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
22	ACRYLIC SEALANT	S/N	\$ 180.00	
23	CAVITY WAX	S/N	\$ 140.00	
24	STONE CHIP	S/N	\$ 180.00	
25	METAL FILLER POWDER	S/N	\$ 280.00	
26	1/4 GLASS SEALANT	S/N	\$ 100.00	
27	LHS REAR TYRE	S/N	TBC	
28	SUNDRIES		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 19,381.00	
TOTAL LABOUR CHARGES		:	\$ 20,072.00	
GRAND TOTAL		:	\$ 39,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT