



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0726/2023/EQ  
**DATE** : 1-Aug-23  
**WIP** : 31360

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/8/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : M/S PREMIUM LEASING PTE LTD  
**ADDRESS** : 9 LENG KEE ROAD  
SINGAPORE 159090

**TELEPHONE** : HP +65 91156516  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : -  
**VEHICLE NO** : **SMA 1237 T**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 28/5/2018  
**ENGINE NO** : CVK 058480  
**CHASSIS NO** : WAUZZZF54JA086555  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 28-Jul-23  
**PLACE OF ACCIDENT** : PRINCE GEORGE'S PARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1237 T**

| S/N                         | NATURE OF JOBS                                                                                                                                                               | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                                            | S/N \$ 360.00 /      |                               |
| 2                           | TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.                                                                                                             | S/N \$ 300.00 /      |                               |
| 3                           | TO INSTALL SOLAR FILM FOR 1/4 GLASS.                                                                                                                                         | S/N \$ 400.00 /      |                               |
| 4                           | TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ 1,600.00 /    |                               |
| 5                           | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                  | S/N \$ 1,600.00 /    |                               |
| 6                           | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                                      | S/N \$ 400.00 X      |                               |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                              | <b>: \$ 4,660.00</b> |                               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1237 T**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 7                           | TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 7,200.00           | 3000                       |
| 8                           | TO RESPRAY REAR BUMPER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL TRIM, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.                                 | \$ 7,500.00           | 2475                       |
| 9                           | TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                       | S/N \$ 520.00         | 280                        |
| 10                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                | S/N \$ 192.00         |                            |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                               | <b>: \$ 20,072.00</b> |                            |





55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1237 T

| S/N                          | PARTS DESCRIPTION                             | QTY | DAMAGED PARTS & PRICES |         |
|------------------------------|-----------------------------------------------|-----|------------------------|---------|
|                              |                                               |     | S/NETT                 | REMARKS |
| 1                            | REAR BUMPER <i>repair</i>                     | 1   | \$ 3,187.00            |         |
| 2                            | REAR BUMPER FIXING PARTS <i>X</i>             | 1   | \$ 289.00              |         |
| 3                            | REAR BUMPER SECURING STRIP <i>X</i>           | 1   | \$ 264.00              |         |
| 4                            | REAR BUMPER CHROME TRIM <i>X</i>              | 1   | \$ 1,206.00            |         |
| 5                            | REAR BUMPER GUIDE SECTION - LH UPPER <i>X</i> | 1   | \$ 27.00               |         |
| 6                            | REAR BUMPER GUIDE SECTION - LH <i>X</i>       | 1   | \$ 52.00               |         |
| 7                            | REAR SIDE PANEL - LH <i>4/</i>                | 1   | \$ 4,315.00            |         |
| 8                            | REAR QUARTER WINDOW - LH <i>m</i>             | 1   | \$ 844.00              |         |
| 9                            | WINDOW PRIMER <i>m</i>                        | 1   | \$ 24.00               |         |
| 10                           | REAR WHEEL HOUSING LINER - LH <i>?</i>        | 1   | \$ 322.00              |         |
| 11                           | ATTACHMENT PARTS <i>see</i>                   | 1   | \$ 144.00              |         |
| 12                           | ADHESIVE TAPES <i>m</i>                       | 1   | \$ 230.00              |         |
| 13                           | REAR DOOR - LH <i>X</i>                       | 1   | \$ 4,210.00            |         |
| 14                           | REAR DOOR OUTER SEAL - LH <i>X</i>            | 1   | \$ 261.00              |         |
| 15                           | BONDING AGENT <i>X</i>                        | 1   | \$ 51.00               |         |
| 16                           | CLEANING SOLUTION <i>X</i>                    | 1   | \$ 80.00               |         |
| 17                           | APPLICATOR <i>X</i>                           | 1   | \$ 9.00                |         |
| 18                           | REAR DOOR CATCH - LH <i>X</i>                 | 1   | \$ 141.00              |         |
| 19                           | REAR DOOR ATTACHMENT PARTS <i>X</i>           | 1   | \$ 141.00              |         |
| 20                           | REAR ALUMINIUM RIM - LH <i>see</i>            | 1   | \$ 2,000.00            |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                               | :   | <b>\$ 17,797.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1237 T

|                             |                                              |     | DAMAGED PARTS & PRICES |                  |
|-----------------------------|----------------------------------------------|-----|------------------------|------------------|
| S/N                         | PARTS DESCRIPTION                            | QTY | S/NETT                 | REMARKS          |
| 21                          | REAR ALUMINIUM RIM RUBBER VALVE <i>per ✓</i> | 1   | \$                     | 4.00             |
| 22                          | ACRYLIC SEALANT <i>per ✓</i>                 | S/N | \$                     | 180.00           |
| 23                          | CAVITY WAX <i>per ✓</i>                      | S/N | \$                     | 140.00           |
| 24                          | STONE CHIP <i>per ✓</i>                      | S/N | \$                     | 180.00           |
| 25                          | METAL FILLER POWDER <i>per ✓</i>             | S/N | \$                     | 280.00           |
| 26                          | 1/4 GLASS SEALANT <i>per ✓</i>               | S/N | \$                     | 100.00           |
| 27                          | LHS REAR TYRE <i>X</i>                       | S/N | TBC                    |                  |
| 28                          | SUNDRIES <i>?</i>                            |     | \$                     | 700.00           |
| <b>TOTAL SPARE PARTS</b>    |                                              | :   | \$                     | <b>19,381.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                              | :   | \$                     | <b>20,072.00</b> |
| <b>GRAND TOTAL</b>          |                                              | :   | \$                     | <b>39,453.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Rosni - HP 90010068

02/08/23 P1115

12 days

EXCESS: 700

Perkins

Resin 5% paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                       |
|-------------------------------|---------------------------------------|
| Owner ID Type:                | Company                               |
| Owner ID:                     | 676M                                  |
| Vehicle No.:                  | SMA1237T                              |
| Vehicle to be Exported:       | No                                    |
| Intended Deregistration Date: | 02 Aug 2023                           |
| Vehicle Make:                 | AUDI                                  |
| Vehicle Model:                | A5 SB 2.0 TFSI S TRONIC (DESIGN)      |
| Primary Colour:               | Blue                                  |
| Manufacturing Year:           | 2018                                  |
| Engine No.:                   | CVK058480                             |
| Chassis No.:                  | WAUZZZF54JA086555                     |
| Maximum Power Output:         | 140.0 kW (187 bhp)                    |
| Open Market Value:            | \$37,959.00                           |
| Original Registration Date:   | 28 May 2018                           |
| First Registration Date:      | 28 May 2018                           |
| Transfer Count:               | 0                                     |
| Actual ARF Paid:              | \$45,143.00                           |
| PARF Eligibility:             | Yes                                   |
| PARF Eligibility Expiry Date: | 27 May 2028                           |
| PARF Rebate Amount:           | \$31,600.00                           |
| COE Expiry Date:              | 27 May 2028                           |
| COE Category:                 | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):            | 10                                    |
| QP Paid:                      | \$38,501.00                           |
| COE Rebate Amount:            | \$18,546.00                           |
| <b>Total Rebate Amount:</b>   | <b>\$50,146.00</b>                    |

The information contained herein is correct as at 02 Aug 2023

OK




# Audi A5 Sportback 2.0A TFSI S-tronic

## Design

**\$119,800** Instalment \$1,654/mth

 Apply for 2.28% loan

 Shortlist

 Get Warranty

 **KONNICHIWA! TOKYO AWAITS!** 

One-way from  
**\$240\*** [Book now](#) \*Taxes included. Terms apply.



### Overview

### Financial

### Photo

### Research

|              |                                                                                                                 |
|--------------|-----------------------------------------------------------------------------------------------------------------|
| Depreciation |  \$20,050 / year               |
| Reg. Date    | 07-Jun-2018<br>(4yrs 10mths 4days COE left)                                                                     |
| Manufactured |  2018                        |
| Mileage      | 96,000 km (18.6k / year)                                                                                        |
| Transmission | Auto                                                                                                            |
| Engine Cap   | 1,984 cc                                                                                                        |
| Road Tax     |  \$1,194 / year              |
| Power        | 140.0 kW (187 bhp)<br>View specs of the <a href="#">Audi A5 Sportback (2017-2020)</a>                           |
| Curb Weight  |  1,535 kg                    |
| COE          |  \$38,600                    |
| OMV          |  \$37,959                    |
| ARF          |  \$45,143                    |
| Dereg Value  |  <b>\$50,238</b> as of today |