

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
6 Raffles Quay
#22-00
Singapore 048580From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loganathan S/O Agoram

Date: 03 Aug 2023

Preliminary Advice

Vehicle No	: GBD3537D	Accident Date	: 19/07/2023
Make	: NISSAN NV350	Policy No.	: -
Assignment Date	: 01/08/2023	Excess	: S\$0.00
Date of Inspection	: 21/07/2023	Est. Duration of Repair	: 5
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,023.42
Revised Amount	:S\$	6,259.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,259.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	5,894.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,106.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.