

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 03 Aug 2023

Preliminary Advice

Vehicle No	: SLG8043U	Accident Date	: 28/07/2023
Make	: NISSAN SYLPHY	Policy No.	: MPC22B00040000
Assignment Date	: 31/07/2023	Excess	: S\$0.00
Date of Inspection	: 03/08/2023	Est. Duration of Repair	: 4
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,076.79
Revised Amount	:S\$	3,300.00
Check Items (Estimated)	:S\$	2,953.57
Total	:S\$	6,253.57

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	28,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,991.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by parts basis,due to no second hand parts available.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.