



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: RODERIC YUEN		Ref: CS3/INC23007774/Tqy3m4 Date: 04/08/2023 Code: INC	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLP 7087C	Veh. Inspected	SMA 8045J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1233753-002	Excess (\$)	0.00
Assign From	NUR ANISAH	Assign Date	01/08/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WDD2050402R134579	Colour	BLUE
Odometer	129765 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information			
Accident Date	25/07/2023	Inspection Date	01/08/2023
Survey held at	25 KAKI BUKIT ROAD 4 #07-38 SYNERGY @ KB		
Repairer	TRIPLE-T AUTOMOBILE		
5a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.		