

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/CT/23007777/4vp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. SNM23D205264

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

7551
214848990

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.


D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



2/8/23 submit P/P \$5761
should be report case video of folder
vehicle hasn't send in for repair

3/8/23

Submit preli report -revised fig \$5761

The vehicle has not send in for repair

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 3/8/23-typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : Ezclaims

Lump Sum / I.B.I. (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	755I
Vehicle Details	
Vehicle No.:	SMY3799Z
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA 2.0 CVT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	4J11DA5046
Chassis No.:	GF7W0701089
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$18,809.00
Original Registration Date:	03 Mar 2021
First Registration Date:	03 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$18,809.00 8404
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2031
PARF Rebate Amount:	\$14,106.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,002.00
COE Rebate Amount:	\$34,884.00
Total Rebate Amount:	\$48,990.00

The information contained herein is correct as at 02 Aug 2023

OK

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



Flexible In-House Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate.
GV Automobile Centre StarAd



Sort by Date Posted 20

2 vehicles



Mitsubishi Outlander

Any Category

Advanced Search



Se

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stz
Search Selection	Mitsubishi Outlander		Any	Any	2021	Any	Any	Any	A
	Mitsubishi	Outlander 2.0A	\$148,800	\$16,700 /yr	29-Sep-2021	1,998 cc	13,000 km	SUV	A
	1 Owner Agent Unit, Super Low Mileage! Fully Maintained At Cycle & Carriage, 10 Year Engine Warranty By C&C! High ARF Unit! Mint Co...								P
	Posted: 01-Aug-2023								
	Mitsubishi	Outlander 2.0A	\$132,800	\$16,390 /yr	08-Feb-2021	1,998 cc	39,384 km	SUV	A
	Super well maintained by previous careful owner with on going warranty and low mileage done, accident free, high trade in with easy in...								
	Dickson Automobile								
	Posted: 27-Jul-2023								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stz
------	-------	-------	--------------	----------	---------	---------	----------	-----

For old advertisements, view Expired ads

20 reset

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Sell by Bidding

Sell by Consignment

Aftermarket

Workshop Directory

Aftermarket Products

Articles

Car Reviews

Car Advice

Car News

Car Features

General

About Us

Contact Us

Careers

Site Map

Resources

COE Prices

Car Loan Calculators

Car Forum

Car Insurance

Car Valuation

COE Renewal

Used Car Warranty

Bidded Carplates

Carpark Rates

Follow Sgcarmart.com



Compare



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DANIAL HARIS	Cust No/Name /DANIAL HARIS
270B PUNGGOL FIELD	Reg No/Reg Date SMY3799Z*# / 03/03/202
#16-235	Date In/Mileage 29/07/2023/ 0
SINGAPORE 822270	Chassis No GF7W0701089
Contact No Mobile: 98279323	Engine No 4J11DA5046
	Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/07/2023/ 12:35	REN	979 / Renemer Ramirez Bag	18183
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 27/07/2023 ALONG JUNC OF COLLYER QUAY & FINLAYSON GREEN					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT VEHICLE					
TP#: SNC3455U TP INS: CHINA TAIPING					
A 10028901					280.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE					
A 54900099					80.00 ✓
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					11 640.00 X
TO TRANSFER RHF DOOR COMPONENTS & MECHANISM					
E PNT88000					2560.00
TO REPLACE FRONT BUMPER,CLIPS,BRACKETS,RH FOG GARNISH,RH MLDG BPR,					
RHF FENDER,RHF WHEEL ARCH,RHF DOOR PNL,RHF SASH TAPE,RHF BELT LINE,					
RHF DOOR GARNISH,RH SIDE AIR DAM,ETC					
STRAIGHTEN,REFORM,ALIGN ON RHF ACCIDENT AFFECTED AREAS					
E PNT98000					2200.00
SPRAY PAINTING ON RHF ACCIDENT AFFECTED AREAS					
(FRONT BUMPER,RHF FENDER,RHF DOOR PANEL)					
E PNT88000					50.00 ✓
TO PERFORM WHEEL BALANCING					
B WHEELALIGNMENT120L					180.00 ✓
TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT					
M SUNDRY					11 X 200.00
TO APPLY BODY SEALANT ON NEW PANELS					
M SUNDRY					11 X 200.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS					
M SUNDRY					11 20 50.00
SUNDRIES					
M SUNDRY					11 X 480.00
YOKOHAMA TYRE 225/55R18					
M FACE,FR BUMPER					1.00 1467.00 00.00 X 1467.00
M CLIP,ENG ROOM COVER					20.00 2.00 00.00 ✓ 40.00 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DANIAL HARIS	Cust No/Name /DANIAL HARIS
270B PUNGGOL FIELD	Reg No/Reg Date SMY3799Z*# / 03/03/202
#16-235	Date In/Mileage 29/07/2023/ 0
SINGAPORE 822270	Chassis No GF7W0701089
Contact No Mobile: 98279323	Engine No 4J11DA5046
	Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CTP00040	Cash	29/07/2023/ 12:35	REN	979 / Renemer Ramirez Bag	18183	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	CLIP,FR BUMPER	nee	10.00	3.00	00.00	✓ 30.00
M	LH SIDE BRACKET,FR BUMPER	11	1.00	19.00	00.00	x 19.00
M	RH SIDE BRACKET,FR BUMPER	nee	1.00	19.00	00.00	✓ 19.00
M	RH FOG GARNISH,FR BUMPER	11	1.00	50.00	00.00	x 50.00
M	RH MOULDING,FR BUMPER	grand	1.00	102.00	00.00	✓ 102.00
M	RH FENDER,FR	n	1.00	722.00	00.00	x 722.00
M	RH MOULDING,FR WHEEL ARCH	grand	1.00	176.00	00.00	✓ 176.00
M	PANEL ASSY,FR DOOR,RH	R	1.00	976.00	00.00	xx 976.00
M	RH TAPE,FR DOOR SASH	11	1.00	53.00	00.00	xx 53.00
M	RH MLDG,F/DR WDO BELT LINE	11	1.00	92.00	00.00	X 92.00
M	RH GARNISH,FR DOOR	grand	1.00	191.00	00.00	✓ 191.00
M	RH AIR DAM,SIDE	grand	1.00	320.00	00.00	✓ 320.00
M	WHEEL,DISC	wheel	1.00	1023.00	00.00	✓ 1023.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-B01
3860

Confirm & accepted by

Nett 12,200.00
8% GST on 12200.00 976.00
Total Payable 13,176.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.