

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004405326-01	Date of Loss:	24/07/2023
Vehicle Reg. No.:	SMQ7860U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOU KAI NING WINSON (CAO KAINING)	Contact No:	+6596999733
Driver:	SOU KAI NING WINSON (CAO KAINING)		

Make/Model:	BMW 428I, 2.0 GRAN COUPE (F36) (A)	Vehicle Reg. Date:	14/08/2015
Vehicle Colour:	RED	Chassis No:	WBA4A52070GA69333
Engine No:	B6030967N20B20A		
Odometer:	159727 KM		
Paint Type:			<i>NOT Notched</i>
Total Loss?	NO		<i>Meowing B4 pain</i>
Est. Duration of Repair (day)	5 ✓		<i>Ex 8600h</i>

Present Location: ACCORD AUTO SERVICES PTE LTD (HQ)**COST OF CLAIMS**

	Amount
Parts	8,222.00
Miscellaneous Items	200.00
Labour	2,220.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,642.00
+ GST 8.00% (S\$)	851.36
Nett Amount (S\$)	11,493.36

This claim is handled by: ADMIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2023)
 Parts: 143 BMW 428i 2.0 Gran Coupe (F36) (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SMQ7860U/01/08/2023 12:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Bu 0.00	0.00	*950.00 F	✓
2	2		*FRONT BONNET HINGE	0.00	0.00	*180.00 F	X
3	2		*FRONT BONNET DAMPER	0.00	0.00	*130.00 F	X
4	1		*FRONT BONNET INSULATOR	0.00	0.00	*130.00 F	X
5	1		*FRONT SUPPORT PANEL TOP	0.00	0.00	*155.00 F	?
6	1		*FRONT SUPPORT CENTRE	0.00	0.00	*100.00 F	?
7	1		*FRONT SUPPORT LOWER	0.00	0.00	*70.00 F	?
8	1		*FRONT BUMPER	Bu 0.00	0.00	*850.00 F	✓
9	2		*FRONT BUMPER SIDE RETAINER LH	Sm 0.00	0.00	*104.00 F	X
10	2		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	*104.00 F	✓
11	1		*FRONT BUMPER CENTRE LH GRILLE	0.00	0.00	*164.00 F	?
12	1		*FRONT BUMPER CENTRE RH GRILLE	0.00	0.00	*164.00 F	✓
13	1		*FRONT BUMPER EMBLEM	0.00	0.00	*75.00 F	✓
14	1		*FRONT BUMPER LOWER GRILLE	Sm 0.00	0.00	*90.00 F	X
15	1		*TOWING COVER	CM 0.00	0.00	*28.00 F	✓
16	2		*REVERSE SENSOR	0.00	0.00	*750.00 F	?
17	2		*REVERSE SEAL	0.00	0.00	*16.00 F	?
18	1		*FRONT REINFORMCENT BAR	0.00	0.00	*330.00 F	?
19	1		*FRONT BUMPER SPONGE	CM 0.00	0.00	*60.00 F	✓
20	1		*FRONT BUMPER TOP RUBBER	0.00	0.00	*100.00 F	?
21	1		*FRONT HEADLAMP LH	0.00	0.00	*1,450.00 F	?
22	1		*FRONT HEADLAMP LOWER BRACKET LH	Sm 0.00	0.00	*175.00 F	X
23	1		*FRONT HEADLAMP RH	0.00	0.00	*1,450.00 F	✓
24	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	*175.00 F	?
25	1		*FRONT LH HEADLAMP NOZZLE COVER	0.00	0.00	*50.00 F	✓
26	1		*FRONT LH HEADLAMP NOZZLE MOTOR	0.00	0.00	*172.00 F	X
27	1		*FRONT BUMPER LOWER	0.00	0.00	*200.00 F	X

F=Franchise part.

Total Parts (\$\$)

8,222.00

Accord Auto Services Pte Ltd/SMQ7860U/01/08/2023 12:35. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

jap

SC

Estimates on Miscellaneous Items

Amount

Qty Particulars

Miscellaneous Items

1	1	FRONT BUMPER CLIPS	Ne	50.00	✓
2	2	FRONT FENDER INNER SHIELD CLIPS	nn	100.00	X
3	1	FRONT NUMBER PLATE WITH HOLDER	CM 45JN	50.00	
Sub Total (S\$)				200.00	

Estimates on Labour

Lab.Type

Amount

No Particulars

Labour Items

1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	6501
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	6001
3	TO CHECK WIRING SYSTEM	New	100.00	201
4	TO APPLY ANTI RUST TREATMENT	New	120.00	nz

Gross Labour Cost (S\$) 2,220.00

Accord Auto Services Pte Ltd/SMQ7860U/01/08/2023 12:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: