

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joey tay

Date: 03 Aug 2023

Preliminary Advice

Insured Vehicle No	: SFE3828L	Accident Date	: 20/04/2023
TP Vehicle No	: FF77B	Assignment Date	: 01/08/2023
Make	: YAMAHA XMAX 300	Est. Duration of Repair	: 2
Date of Inspection	: 31/07/2023		
Inspection At	: IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ) 25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,592.28
Revised Amount	:S\$	1,085.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,085.58

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.