

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

27 JUL 2023

Vehicle No: FF77B

Model : YAMAHA X-MAX300

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMT S\$</u>
<u>List Items</u>		
1	Rear Muffler <i>R</i>	\$ 763.00 <i>X</i>
1	Rear Muffler Protector <i>grotel</i>	\$ 239.20 <i>/</i>
1	Rear Foot Rest <i>twi</i>	\$ 63.70 <i>/</i>
1	Rear Foot Rear Bracket <i>one</i>	\$ 37.90 <i>/</i>
<i>Rest</i>	1 Rear Foot Rest Pin <i>twi</i>	\$ 18.30 <i>/</i>
<i>Rest</i>	1 Rear Foot Rest Board <i>grotel</i>	\$ 195.10 <i>/</i>
1	Rear Tailside Cover Top <i>grotel</i>	\$ 237.80 <i>/</i>
1	Rear Tailside Cover Lower <i>grotel</i>	\$ 214.20 <i>/</i>
		<hr/>
		\$ 1,769.20
	Less 10%	\$ 176.92
		<hr/>
		\$ 1,592.28
<u>Labour Charges</u>		
1	To provide Labour	\$ 500.00 <i>180</i>
1	Tp respray painting <i>11</i>	\$ 500.00 <i>X</i>
		<hr/>
		\$ 1,000.00

*Not Allowed
 hr
 3/17/23
 P/P \$1085.58
 2 days
 when the after rep-*

Grand Total: \$ 2,592.28

*P-1006.2
 102
 905.58
 180
 1085.58*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: