

Surveyor:

Date: 01/08/2023
 Vehicle No: SNH8064E
 Model: BYD E6
 Chassis: LC0CE4DC5N0270042-2022
 Reg.Year: 2022

Third Party Insurer: AIG
 Third Party Veh No: GZ7750C
 Date of Accident: 26/07/2023
 Estimator: TING AN
 Surveyor:


LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00 ?
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	\$700.00 60d
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	\$150.00 120d
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00 60d
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00 50d
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00 ?
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$100.00 ?
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00 20d

LABOUR TOTAL \$2,090.00

TING AN

TOTAL \$13,167.00



Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

