

INC

Category	Value
1. TOTAL	100

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC3371z

25.07.2023

MAKE/REG 28.02.2020

CHIANG/income

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER CLIPS		
1	REAR BUMPER		\$503.04
1	REAR BUMPER RETAINER LH		\$112.70
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT		\$378.32
1	REAR BUMPER LOWER COVER		\$654.96
1	REAR BUMPER REFLECTOR RH		\$55.00
1	TAIL LAMP LOWER rH		\$570.00
	SUB TOTAL		\$2,296.02
	25.00%		\$574.00
	DISCOUNTED TOTAL		\$1,722.01
1	REAR REVERSE SENSOR		\$135.70
1	REAR BUMPER MAT		\$50.00
			\$185.70
	Labour Charge		
	Panel Beating		\$700.00
	Spray Painting Charge		\$300.00
	Tuff Kote		\$60.00
	Remove and Refix Reverse Sensor		\$60.00
	TOTAL LABOUR		\$1,120.00
	ESTIMATE TOTAL		\$3,027.71
A			
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

fuyhi 9749579
 W 1/8/23 @ 1230
 02 day
 45 days after repair
 fuyhi @ (Klempen)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Team: ARC Repair TP(CLSO)1	JOB CARD Sales Order: 5906011	JC NO305562193
STOMER	REGN NO.: SHC3371Z	MILEAGE
MS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL E. 1/2 F
STOMER NO. 7010045	MODEL PRIUS HYBRID(G4A31.07.2023 09:25	DATE/TIME IN
DRESS 383 SIN MING DRIVE	YR OF MANU. 28.02.2020	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE JTDKB3FU203091155	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 29.07.2023
NATURE: 3P 29.07.2023

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:		CUSTOMER'S SIGNATURE	
SERVICE ADVISOR			
Wedgement Slip		Exit Pass	
No.: SHC3371Z	CHIANG	Vehicle No.: SHC3371Z	
of Service Advisor	Signature/Date	Name of Service Advisor	Date
returned to Service Reception upon collection		To be kept by Security Guard	