

ASS. REC. BY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Guany

Veh No: SMC/562C Yr Regn: 2020, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 242263 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HCS5/CV64189360

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: L95/65R15

R: 15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Winfarke

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 01/08/23

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee:

Transportation:

\$ + RS _____ SI

Photos

Others

Rep. Format: _____

Lump Sum / L.B.B. /

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

COMFORTDELORO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1562C

26.07.2023

MAKE REG.

MODEL IONIQ G2

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER			X \$481.10
1	FRONT BUMPER BRACKET TOP LH		\$35.00	X \$350.00
10	FRONT BUMPER CLIPS		\$2.20	X \$22.00
1	FRONT BUMPER GRILLE LH			X \$368.50
1	FRONT DOOR CAP COVER			Ry \$346.40
1	FRONT FENDER LH			Ht \$588.80
1	FRONT FENDER EMBLEM LH			nel \$26.60
1	FRONT WING MIRROR LH			Ry \$1,391.70
1	FRONT DOOR MOULDING			cut \$110.00
1	REAR DOOR MOULDING			cut \$125.00
1	ROCKER GARNISH LH			Ry \$290.00
	SUB TOTAL			\$4,100.10
	20.00%			\$773.02
	DISCOUNTED TOTAL			\$3,092.08
1	FRONT DOOR COMFORT LOGO			nel \$75.00
				\$67.50
	Labour Charge			
	Panel Beating		panel beat - 525	\$600.00
	Spray Painting Charge		Spray - 000	\$700.00
	Check Wiring			\$90.00
			wiring - X	\$60.00
	TOTAL LABOUR			\$1,450.00
	ESTIMATE TOTAL			\$4,609.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanf'hu 97445777
 WP 1/8/23 @ 1230pm
 L/S Body after repair
 Tanf'hu at dealer
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date/Time: 01.08.2023 08:02

Page : 1

JOB CARD Sales Order: 5906082

JC NO 305562306

Team: ARC Repair TP(CLSO)1

TOMER

VS COMFORT TRANSPORTATION PTE LTD
TOMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)REGN NO.:
SHC1562CMAKE:
HYUNDAIMODEL
IONIQ(G3)YR OF MANU.
27.02.2020CHASSIS CODE
KMHC851CVLU189360

MILEAGE

FUEL

E.....1/2.....F

DATE/TIME IN
31.07.2023 12:25

TARGET DATE

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 26.07.2023

Signature: 3P 26.07.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SHC1562C

CHIANG

Name of Service Advisor

To be returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC1562C

Name of Service Advisor

To be kept by Security Guard

Date