### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 (Claims & Performance

Management) Singapore 068897 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH 04 Aug 2023 Date:

## **Preliminary Advice**

Vehicle No : SNB3337H Accident Date : 22/07/2023 Policy No. Make : HONDA VEZEL HYBRID : SP2004584418-01

Assignment Date : 01/08/2023 Excess : S\$2,000.00 : 6

Date of Inspection : 02/08/2023 Est. Duration of Repair

Inspection At : VIN'S MOTOR PTE LTD (SIN MING)

160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY

SINGAPORE 575722

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,030.00 (Estimate \$13,920.00 + Supplementary \$110.00)
Revised Amount	·S\$	10 680 00

Check Items (Estimated) :S\$ 0.00 Total :S\$ 10,680.00

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 107,000.00 COE / PARF Rebate :S\$ 42,861.00

Salvage Value :S\$

Margin for Repair :S\$ 64,139.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amour	it. We have also	confirmed excess	s and policy coveraເ	ge. Kindly
	let us have your authorisation.				

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS. ( X )