

ASS. FIC. BY:

REF:

CS/AIS23007819/D9P3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 6 days Res.: Yes or No

Lum Sum: ?? % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 8NB 3337H Yr Regr: Sept 2020

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel CC 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 223948 T/Radio: Insured / Std / NI / NA

Eng/No: LEB 674 0045

C/No: RU3132.0032

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 16

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokmana

Front _____ Rear _____

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 22/07/2023 D.O.L. 02/08/2023

Survey held at Vins Man Sun Ming

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
	<u>Allianz OD</u>
	<u>MD 107K</u>
	<u>LIA 42.8K</u>
	<u>NL 64.2K</u>

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos: _____

Others: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Report Format: _____

1 minor. 9 cur. 11 P to 1%

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : OD/072023/6434
Date : 24-07-2023
Accident Date : 22-07-2023

Vehicle Details

Make & Model : HONDA VEZEL HYBRID 1.5X
AUTO
Chassis No : RU31320032
Registration No : SNB3337H

S/N	Description	Qty	Amount (S\$)
1	FRONT BONNET <i>typ</i>	1.00	\$510.00 <i>X</i>
2	BONNET LOCK <i>sc</i>	1.00	\$70.00 <i>X</i>
3	BONNET LOCK BRACKET <i>crack</i>	1.00	\$30.00 <i>✓</i>
4	FRONT GRILLE BASE <i>broken</i>	1.00	\$250.00 <i>✓</i>
5	FRONT GRILLE EMBLEM <i>sc</i>	1.00	\$20.00 <i>X</i>
6	FRONT GRILLE OUTER GARNISH <i>broken</i>	1.00	\$240.00 <i>✓</i>
7	FRONT GRILLE RH SUPPORT BRACKET <i>sc</i>	1.00	\$10.00 <i>X</i>
8	FRONT GRILLE LH SUPPORT BRACKET <i>broken</i>	1.00	\$10.00 <i>X</i>
9	RH HEADLAMP <i>minority crack</i>	1.00	\$1,100.00 <i>✓</i>
10	LH HEADLAMP <i>minority crack</i>	1.00	\$1,100.00 <i>✓</i>
11	RH HEADLAMP LOWER BRACKET <i>?</i>	1.00	\$30.00 <i>?</i>
12	LH HEADLAMP LOWER BRACKET <i>?</i>	1.00	\$30.00 <i>?</i>
13	FRONT BUMPER <i>horn</i>	1.00	\$440.00 <i>✓</i>
14	FRONT BUMPER TOWING COVER <i>hm</i>	1.00	\$20.00 <i>X</i>
15	FRONT BUMPER CENTER LOWER GRILLE <i>broken</i>	1.00	\$70.00 <i>✓</i>
16	FRONT BUMPER RH FOG LAMP <i>hm</i>	1.00	\$170.00 <i>X</i>
17	FRONT BUMPER LH FOG LAMP <i>hm</i>	1.00	\$170.00 <i>X</i>
18	FRONT BUMPER RH FOG LAMP COVER <i>hm</i>	1.00	\$30.00 <i>X</i>
19	FRONT BUMPER LH FOG LAMP COVER <i>hm</i>	1.00	\$30.00 <i>X</i>
20	FRONT BUMPER LOWER PAD <i>minority broken</i>	1.00	\$260.00 <i>✓</i>
21	FRONT BUMPER RH SIDE RETAINER <i>sc</i>	1.00	\$20.00 <i>X</i>
22	FRONT BUMPER LH SIDE RETAINER <i>sc</i>	1.00	\$20.00 <i>X</i>
23	FRONT BUMPER REINFORCEMENT <i>Reinforced</i>	1.00	\$220.00 <i>✓</i>
24	FRONT BUMPER LOWER LIP <i>sc</i>	1.00	\$80.00 <i>X</i>
25	FRONT BUMPER UNDER COVER <i>broken</i>	1.00	\$80.00 <i>✓</i>
26	FRONT BUMPER CLIPS <i>hm</i>	10.00	\$20.00 <i>✓</i>
27	FRONT SUPPORT PANEL <i>?</i>	1.00	\$380.00 <i>?</i>
28	FRONT SUPPORT PANEL TOP COVER <i>hm</i>	1.00	\$70.00 <i>X</i>
29	FRONT SUPPORT PANEL TOP COVER CLIPS <i>sc</i>	10.00	\$20.00 <i>X</i>
30	FRONT RADAR <i>hm ?</i>	1.00	\$1,300.00 <i>X ?</i>

31	FRONT RADAR BRACKET <i>vt</i>	1.00	\$480.00	✓
32	AIRCON CONDENSER <i>vt</i>	1.00	\$510.00	✓
33	AIRCON CONDENSER RECEIVER PIPE <i>HN</i>	1.00	\$80.00	✗
34	AIRCON CONDENSER DISCHARGE PIPE <i>HN</i>	1.00	\$130.00	✗
35	AIRCON CONDENSER SUCTION PIPE <i>HN</i>	1.00	\$120.00	✗
36	AIRCON CONDENSER FAN MOTOR <i>HN</i>	1.00	\$190.00	✗
37	AIRCON CONDENSER FAN BLADE <i>HN</i>	1.00	\$40.00	✗
38	AIRCON CONDENSER FAN COWLING <i>HN</i>	1.00	\$70.00	✗
39	RADIATOR <i>vt</i>	1.00	\$920.00	✓
40	RADIATOR TOP HOSE <i>HN</i>	1.00	\$30.00	✗
41	RADIATOR LOWER HOSE <i>?</i>	1.00	\$30.00	?
42	RADIATOR FAN MOTOR <i>HN HN</i>	1.00	\$220.00	✗
43	RADIATOR FAN BLADE <i>?</i>	1.00	\$40.00	?
44	RADIATOR FAN COWLING <i>?</i>	1.00	\$70.00	?
45	RADIATOR RH SIDE GUIDE <i>?</i>	1.00	\$920.00	?
46	RADIATOR LH SIDE GUIDE <i>?</i>	1.00	\$30.00	?
47	HORN - HIGH <i>crack</i>	1.00	\$30.00	✓
48	HORN - LOW <i>HN</i>	1.00	\$220.00	✗
			\$10,930.00	
49	FRONT NO. PLATE <i>crack vt</i>	1.00	\$40.00	✓
50	COOLANT <i>HN</i>	1.00	\$80.00	✗
51	TO REFILL AIRCON GAS	1.00	\$150.00	120/-
52	TO RESET HEADLAMP SYSTEM	1.00	\$280.00	180/-
53	TO RESET RADAR SYSTEM	1.00	\$380.00	800/-
54	TO REPAIR DAMAGES	1.00	\$980.00	800/-
55	TO SPRAY PAINTING	1.00	\$1,080.00	800/-
Subtotal w/o GST:			\$13,920.00	

02/08/2023 @ 1100am

Hot Aircon

9/Part.

6 days

Excess 21000/-

Part by me

Paint

with

Part.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 077I

Vehicle Details

Vehicle No.: SNB3337H
Vehicle to be Exported: No
Intended Deregistration Date: 24 Jul 2023
Vehicle Make: HONDA
Vehicle Model: VEZEL HYBRID 1.5X AUTO
Primary Colour: Grey
Secondary Colour: Purple
Manufacturing Year: 2018
Engine No.: LEB6740045
Chassis No.: RU31320032
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$25,701.00
Original Registration Date: 25 Sep 2020
First Registration Date: 25 Sep 2020
Transfer Count: 1
Actual ARF Paid: \$17,982.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Sep 2030
PARF Rebate Amount: \$13,486.00

Intended COE Rebate Details

COE Expiry Date: 24 Sep 2030
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$40,989.00
COE Rebate Amount: \$29,375.00
Total Rebate Amount: \$42,861.00

The information contained herein is correct as at 24 Jul 2023

OK