




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS3/HSB23007823/Tqp3m4 Date: 04/08/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHA 8817H	Veh. Inspected	PPH 8557	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S3M04OFI	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	02/08/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDD2050776L050472	Colour	BLACK	
Odometer	73960 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	MICHELIN	6 mm	
L/H Front Tyre	245/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	27/07/2023	Inspect Date / Time	02/08/2023 (03:15 PM)	
Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$16,000-\$18,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	

Report Ref No. CS3/HSB23007823/Tqp3m4

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.