

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Email/Fax No:

Contact No:

Vehicle No:

SLW8811K

Brand & Model:

PORSCHE MACAN

Chassis/VIN No:

WP1ZZZ95ZHLB22076

WIP#:

49176

Date:

1-Aug-23

Franchise:

PORSCHE MACAN

Contact Person (Eurokars):

VICTOR

Contact No (Eurokars):

6331 0680

Type of Claim:

OWN DAMAGE

YEAR MODEL:

07/10/2016

PARTS / MATERIAL CHARGES				MARK = Survey Marking [Key "A" if item is approved]		
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	DOOR SHELL (RH) - FRONT DOOR <i>Low repair</i>	P95B-831-022-B -GRV	1		-	\$ 2,474.40
2	Sound absorber - FRONT RH DOOR <i>AX</i>	PPAB-837-833- -	2		-	\$ 70.20
3	DOOR SEAL OUTER <i>AX</i>	P95B-837-911- -	1		-	\$ 280.90
4	DOOR SEAL LOWER <i>AX</i>	P95B-837-120-B -	1		-	\$ 164.40
5	(WH03) Seal WEBING TAPE <i>AX</i>	PAKL-437-D40- -	4		-	\$ 4.80
6	STOPPER GROMMET <i>?X</i>	P191-971-908- -	4		-	\$ 35.60
7	GASKET DOOR <i>AX</i>	P999-911-659-40-	2		-	\$ 2.80
8	BLACK COVER MOULDING - FRONT RH <i>SCA</i>	P95B-898-562- -OK1	1		-	\$ 678.10
9	BLACK COVER MOULDING - REAR RH <i>de</i>	P95B-898-566- -OK1	1		-	\$ 646.60
10	REPAIR KIT ADHENSIVE TAPE DOOR - RH FRONT/REAR <i>mu</i>	P95B-898-634- -	1		-	\$ 124.60
11	STONE GUARD FILM RH <i>mu</i>	P95B-854-932-A	1		-	\$ 99.30
12	DOOR SHELL (REAR RH DOOR) <i>mu</i>	P95B-833-022-B -GRV	1		-	\$ 2,428.20
13	DOOR SEAL OUTER <i>mu</i>	P95B-839-911- -	1		-	\$ 274.00
14	DOOR SEAL *C SHAPE* <i>mu</i>	P95B-839-762-B -	1		-	\$ 210.20
15	DOOR SEAL LOWER <i>mu</i>	P95B-839-120-B -	1		-	\$ 159.70
16	STOPPER GROMMET <i>mu</i>	P191-971-908- -	2		-	\$ 17.80
17	GASKET DOOR <i>mu</i>	P999-911-659-40-	4		-	\$ 5.60
18	BLACK SILL COVER - SIDE STEP MOULDING (RH) <i>de</i>	P95B-853-564- -1E0	1		-	\$ 295.70
19	Sound absorber FOR SIDE STEP MOULDING RH <i>mu</i>	P95B-857-993-A -	2		-	\$ 89.00
20	ALLOY WHEEL <i>SCA</i>	P95B-601-025-DT-JE1	1		-	\$ 3,872.80
21	SENSOR TPM (433MHz) <i>?</i>	PPAB-907-275- -	1		-	\$ 372.10
22	ALU TYRE PRESS VALVE (W) <i>?</i>	P9P1-601-361-F -	1		-	\$ 75.20
23	SCREW (WJ02) <i>?</i>	P4D0-601-365- -	1		-	\$ 12.30
24	Black WHEEL COVER (rear RH) <i>SCA</i>	P95B-853-828-A -1E0	1		-	\$ 56.10
25					-	\$ -
26					-	\$ -
27					-	\$ -
28					-	\$ -

Sub-Total (Parts Price) \$ - \$ **12,450.40**
LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE

REPAIR ESTIMATE

1	TO REMOVE /REPLACE FRONT & REAR RH DOOR. TO TRANSFER ALL MECHANISM TO NEW PART. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	4680	\$ 7,880.00
2	TO RESPRAY FRONT RH & REAR RH DOOR & REAR RH QUARTER PANEL & REAR BUMPER .	5200	\$ 5,800.00
3	TO REMOVE & REFIX REAR SEAT AND REPAIR & KNOCK REAR RHS C-PILLAR	1560	\$ 2,340.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	nett	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	nett	\$ 680.00
7	TO TRANSFER THE DOOR MECHANISM.	nett	\$ 390 780.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
10	SUNDRIES.	nett	\$ 20 58.00

Survey Date & Time: 03/08/23 @ 14:30 Repair Days: 6 days Excess: TRA

Surveyor Remarks:

Ross
HP 90010088
~~Excess~~: REPAIR
Peg 54 paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 18,470.00

	REVISED	PRICE
Parts Price	\$ -	\$ 12,450.40
Labour Price	\$ -	\$ 18,470.00
Total (Initial Estimate)	\$ -	\$ 30,920.40
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 30,920.40
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 30,920.40
GST 8%	\$ -	\$ 2,473.63
GRAND TOTAL	\$ -	\$ 33,394.03

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: