



205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP(ALLIANZ)Vehicle No. : SNG8819AMake & Model : TOYOTA SIENTAYear of Manufacture : 2022Chassis No. : NHP17072397Ins Company : IIIEngine No. : 1NZ9412548

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 28/7/2023

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Case Owner : KELVIN

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 5,606.00Plus/Less 25% \$ 1,401.50Total of Cost / List \$ 4,204.50

(b) Nett Price Items \_\_\_\_\_

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 85.00Total Parts Cost (Appendix A) \$ 4,289.50Labour (Appendix B) \$ 1,740.00Total Repair Cost \$ 6,029.50**Operation**

KELVIN SU TEL:97864236 E:kelvinsukwen@cdge.com.sg

JOHARI BH TEL:97213705 E:joharibh@sparkcarcare.com

OI SUN PIN TEL: 97288916 E: oisunpin@cdge.com.sg

*The above total will be subjected to 8% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No : **SNG8819A** Case Owner : **KELVIN**

Make & Model : **TOYOTA SIENTA** Year Manufacture : **2022**

Chassis No : **NHP17072397** Engine No : **1NZ9412548**

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : **KELVIN** Type of Claim : **TP(ALLIANZ)**

S/No	Part Description	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1		\$ 849.00		
2	REAR BUMPER GARNISH	1		\$ 235.00		
3	REAR BUMPER SIDE GARNISH-LH	1		\$ 126.00		
4	REAR BUMPER CLIPS	10		\$ 55.00		
5	REAR END PANEL	1		\$ 650.00		
6	REAR END PANEL TRIM BOARD	1		\$ 203.00		
7	LUGGAGE FLOOR BOARD	1		\$ 672.00		
8	REAR TAILGATE	1		\$ 1,235.00		
9	REAR TAILGATE INNER BOARD	1		\$ 246.00		
10	TAILGATE WEATHERSTRIP	1		\$ 403.00		
11	TAILGATE GARNISH	1		\$ 252.00		
12	REAR W/S MOULDING	1		\$ 250.00		
13	EMBLEM "TOYOTA"	1		\$ 75.00		
14	EMBLEM "HYBRID"	1		\$ 65.00		
15	REVERSE SENSOR	1		\$ 290.00		
16	SEALANT	1			\$ 40.00	
17	REAR NO.PLATE	1			\$ 45.00	
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u><b>SNG8819A</b></u>	Case Owner	: <u><b>KELVIN</b></u>
Make & Model	: <u><b>TOYOTA SIENTA</b></u>	Year of Manufacture	: <u><b>2022</b></u>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*