

ASS. REC. BY: Taufik

REF:

CS/ TM / 23007840/Tvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBB 8334APolicy No. M2304425Claims No. M2304425

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seer _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Merimen Vehicle: IN / OUTVeh No: SHC 7699C Yr Regn: 2491 NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Lorry c.c. 1580.Colour: Yellow A/G: Insured / Std / NI / NASp. Reading: 361945 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC 851 CV 64185686Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 175/65R15R: 175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 2/8/2023 D.O.I. 2/8/23Survey held at Lampit Lorry

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Frt N/S

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/8/23 Taufikh confirmed LS \$3550 (Red 1701.04, 32%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) 7/8/23-typist

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Wheel-end (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Rep. Formet: MerimenLump Sum / F.F. : \$3550

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

ICIX
Jumani (Lum)

TP INSURER:
CCPL

Singapore

Tokio Marine Insurance Singapore Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/08/2023
Vehicle Reg. No.:	SHC7699C	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	27/11/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU389018	Chassis No:	KMHC851CVLU183686
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	
Miscellaneous Items	2,980.60
Labour	11.00
Paintwork Labour	1,500.00
Towing	0.00
	0.00
Gross Total (S\$)	4,491.60
+ GST 8.00% (S\$)	359.33
Nett Amount (S\$)	4,850.93

this claim is handled by: JUMANI BIN MASUDIN

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	de ✓ *481.10 FL
2	10		*FRT BUMPER CLIPS	20.00	0.00	key ✓ *22.00 FL
3	1		*FRT BUMPER CENTRE MOULDING	20.00	0.00	ent ✓ *368.50 FL
4	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	? ✓ *35.00 FL
5	1		*HEADLAMP ASSY LH	20.00	0.00	key ✓ *2,110.30 FL
6	1		*FRT FENDER LH	20.00	0.00	RY ✓ *588.80 FL
7	1		*FRT FENDER EMBLEM LH	20.00	0.00	key ✓ *26.60 FL
8	1		*FRT FOG LAMP GRILLE LH	20.00	0.00	key ✓ *93.45 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,725.75
- List Item Discount on L Items (S\$)	745.15
Total Parts (S\$)	2,980.60

ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 525	800.00
2	SPRAY PAINT	New 500	600.00
3	CHECK WIRING	New 30	50.00
4	TUFF KOTE	New 207	50.00
Gross Labour Cost (S\$)			1,500.00

ComfortDelGro Engineering Pte Ltd/SHC7699C/02/08/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
WP 2/8/23 C
USK survey after repair
Tanpin Effkembu
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609288

Date/Time: 02.08.2023 15:05

Page : 1

am: ARC Repair TP(CFS0)1

JOB CARD Sales Order: 5906423


JC NO305562534

OMER S CITYCAB PTE LTD OMER NO 7010070 IESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) JUNT CARD NO.	REGN NO.: SHC7699C	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3) 02.08.2023 10:50	DATE/TIME IN
	YR OF MANU. 27.11.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU183686	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 02.08.2023
 Accurrence: 3P.02.08.23

NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Signature Slip

Exit Pass

Vehicle No.: SHC7699C

JU TOKIO

Vehicle No.:

SHC7699C

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard