

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0731/2023/EQ
DATE : 3-Aug-23
WIP : 31559

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY ON 07/08/2023.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. TAN KONG HUI
ADDRESS : BLK 185 PASIR RIS STREET 11
#02-62
SINGAPORE 510185
TELEPHONE : HP +65 96646300
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070111159-03
VEHICLE NO : **SFN 8088 A**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S-TRONIC
MODEL YEAR : 27/7/2020
ENGINE NO : DKY 011907
CHASSIS NO : WAUZZZF24LN048714
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-23
PLACE OF ACCIDENT : PASIR RIS ST 11, TURNING RIGHT INTO CLUSTER OF
BLOCKS TO BLK 185

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFN 8088 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	
3	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$	600.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	
SUB-TOTAL LABOUR CHARGES		:	\$	3,440.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFN 8088 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	
8	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	
9	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	
10	TO RESPRAY REAR BUMPER, RHS REAR DOOR, DOOR HANDLE, FUEL FILLER CAP, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL AND REAR END PANELLING.	\$	6,500.00	
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$	19,612.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8088 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,187.00	
2	REAR BUMPER FIXING PARTS	1	\$ 259.00	
3	REAR BUMPER SECURING STRIP	1	\$ 204.00	
4	REAR BUMPER GUIDE SECTION - RH LOWER	1	\$ 75.00	
5	REAR BUMPER GUIDE PROFILE - RH	1	\$ 79.00	
6	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$ 54.00	
7	REAR PARKING AID SENSOR - RH	1	\$ 299.00	
8	REAR PARKING AID SEAL RING	4	\$ 11.00	
9	REAR SIDE PANEL - RH	1	\$ 5,559.00	
10	REAR WINDOW HEATED	1	\$ 1,385.00	
11	REAR QUARTER WINDOW	1	\$ 834.00	
12	WINDOW PRIMER	2	\$ 47.00	
13	REAR WHEEL HOUSING LINER	1	\$ 322.00	
14	REAR WHEEL SPOILER - RH	1	\$ 196.00	
15	REAR WHEEL SPOILER STONE CHIP GUARD - RH	1	\$ 60.00	
16	ATTACHMENT PARTS	1	\$ 144.00	
17	ADHESIVE TAPES	1	\$ 68.00	
18	REAR FUEL INSERT	1	\$ 114.00	
19	REAR DOOR - RH	1	\$ 4,750.00	
20	REAR DOOR OUTER SEAL	1	\$ 223.00	
SUB TOTAL SPARE PARTS		:	\$ 17,870.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8088 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR SEAL BRACKET - RH	1	\$ 204.00	
22	REAR DOOR STONE CHIP PROTECTION FILM - RH	1	\$ 146.00	
23	REAR DOOR CATCH - RH	1	\$ 141.00	
24	REAR DOOR HANDLE CHROME TRIM PLATE - RH	1	\$ 116.00	
25	REAR DOOR HANDLE CHROME CAP - RH	1	\$ 111.00	
26	REAR ALUMINIUM RIM - RH	1	\$ 1,955.00	
27	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
28	1/4 GLASS SEALANT	S/N	\$ 100.00	
29	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
30	ACRYLIC SEALANT	S/N	\$ 180.00	
31	CAVITY WAX	S/N	\$ 140.00	
32	STONE CHIP	S/N	\$ 180.00	
33	METAL FILLER POWDER	SN	\$ 280.00	
34	SUNDRIES		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 22,327.00	
TOTAL LABOUR CHARGES		:	\$ 19,612.00	
GRAND TOTAL		:	\$ 41,939.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT