

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III23004930/DNY3M4-1**Date:** 04/08/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571  
**Claimant Vehicle No :** FBM5081R **Insured Vehicle No :** SLM2941K  
 Date of Loss: 05/05/2023 Nature of Claim: TP Claim No: MFL2023D0004877

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBM5081R**  
 Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0320715  
 Reg. Date: 01/12/2017 (Man. Year: 2017) Chassis No: MH3UG0740H0067320  
 Colour: Multi-colour Odometer: 0 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 80-90-17 Rear Tyre Size: 110-70-17  
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 3,372.10          | 1,087.60          | 2,284.50          | 67.75         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 980.00            | 360.00            | 620.00            | 63.27         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,352.10</b>   | <b>1,447.60</b>   | <b>2,904.50</b>   | <b>66.74</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>1,150.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>4,352.10</b>   | <b>1,150.00</b>   | <b>3,202.10</b>   | <b>73.58</b>  |

**INSPECTION**

Date of Assignment: 03/08/2023  
 Date Inspected: 15/05/2023 Inspected At: SPEEDY MOTOR CYCLE SERVICE CENTRE  
 10 ANG MO KIO IND PARK 2A #05-21  
 SINGAPORE 568047  
 Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                            |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 04 Aug 2023)                                                                                                                                             |                                                            |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | YAMAHA SNIPER T150 150cc (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                          |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBM5081R)                                                                                                                                    |                                                            |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                            |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                            |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                   | Condition                 | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------------------|---------------------------|------------|------------|
| 1   | 1   |          | *HANDLE BAR                                   | Distorted                 | 85.00 FL   | *85.00 FL  |
| 2   | 1   |          | *SET HANDLE GRIP                              | Cut                       | 30.00 FL   | *30.00 FL  |
| 3   | 1   |          | *CLUTCH LEVER                                 | Not Necessary             | 28.00 FL   | *- FL      |
| 4   | 1   |          | *BRAKE LEVER                                  | Cut/Bent                  | 28.00 FL   | *28.00 FL  |
| 5   | 1   |          | *PAIR MIRROR                                  | Cut                       | 96.00 FL   | *48.00 FL  |
| 6   | 1   |          | *FRONT COWLING COMPLETE                       | Cut                       | 165.00 FL  | *165.00 FL |
| 7   | 1   |          | *FRONT INNER PANEL                            | Not Necessary             | 116.00 FL  | *- FL      |
| 8   | 1   |          | *FRONT STAY                                   | Not Necessary             | 65.00 FL   | *- FL      |
| 9   | 1   |          | *FRONT FENDER                                 | Not Necessary             | 122.00 FL  | *- FL      |
| 10  | 1   |          | *FRONT SIDE COVER COMPLETE @148.00<br>2PIECES | Cut (1Piece Only)         | 296.00 FL  | *148.00 FL |
| 11  | 2   |          | *FRONT SIGNAL LIGHT @56.00                    | Not Necessary             | 112.00 FL  | *- FL      |
| 12  | 1   |          | *GEAR SHIFT PEDAL                             | Not Necessary             | 59.00 FL   | *- FL      |
| 13  | 1   |          | *BRAKE PEDAL                                  | Cut                       | 62.00 FL   | *62.00 FL  |
| 14  | 1   |          | *PAIR FRONT FOOTREST                          | Cut                       | 110.00 FL  | *110.00 FL |
| 15  | 1   |          | *FRONT FOOTREST BAR                           | Bent                      | 72.00 FL   | *72.00 FL  |
| 16  | 1   |          | *PAIR REAR FOOTREST                           | Not Necessary             | 96.00 FL   | *- FL      |
| 17  | 1   |          | *REAR COVER COMPLETE @126.00<br>2PIECES       | Cracked/Cut (1Piece Only) | 252.00 FL  | *126.00 FL |
| 18  | 1   |          | *REAR FENDER COMPLETE                         | Bent                      | 126.00 FL  | *126.00 FL |
| 19  | 1   |          | *REAR FENDER BRACKET                          | Not Necessary             | 42.00 FL   | *- FL      |
| 20  | 1   |          | *SWINGARM COMPLETE                            | Not Necessary             | 449.00 FL  | *- FL      |
| 21  | 1   |          | *REAR WHEEL COMPLETE                          | Not Necessary             | 396.00 FL  | *- FL      |
| 22  | 1   |          | *REAR WHEEL AXLE                              | Not Necessary             | 45.00 FL   | *- FL      |
| 23  | 1   |          | *MUFFLER ASSY                                 | Not Necessary             | 485.00 FL  | *- FL      |
| 24  | 1   |          | *MUFFLER GASKET                               | Not Necessary             | 18.00 FL   | *- FL      |
| 25  | 1   |          | *MUFFLER PROTECTOR                            | Cut                       | 72.00 FL   | *72.00 FL  |
| 26  | 1   |          | *MUFFLER CAP                                  | Cut                       | 42.00 FL   | *42.00 FL  |
| 27  | 1   |          | *SET STEERING CONE & BEARING                  | Necessary                 | 80.00 FS   | *65.00 FS  |
| 28  | 1   |          | *REAR NUMBER PLATE                            | Deformed                  | 20.00 FS   | *20.00 FS  |
| 29  | 1   |          | *REAR RACK                                    | Not Necessary             | 150.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>3,719.00</b> | <b>1,199.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 346.90          | 111.40          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,372.10</b> | <b>1,087.60</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                                 | Lab.Type | Repairer's    | Amount        |
|---------------------------------|---------------------------------------------|----------|---------------|---------------|
| <b>Labour Items</b>             |                                             |          |               |               |
| 1                               | TOWING FEE                                  | New      | 80.00         | 60.00         |
| 2                               | REPAIR FORK & ALIGN STEERING COMPONENTS     | New      | 200.00        | 0.00          |
| 3                               | ALIGN SWINGARM & REBALANCE REAR WHEEL       | New      | 200.00        | 0.00          |
| 4                               | RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS | New      | 500.00        | 300.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                             |          | <b>980.00</b> | <b>360.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >