

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 04 Aug 2023

Preliminary Advice

Vehicle No	: SNJ8627X	Accident Date	: 20/07/2023
Make	: MERCEDES-BENZ SLK280	Policy No.	: SP2004987143-01
Assignment Date	: 03/08/2023	Excess	: S\$2,000.00
Date of Inspection	: 03/08/2023	Est. Duration of Repair	: 7
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.

Repairer's Estimate (Gross)	:S\$	6,900.00 (LABOUR ONLY)
Revised Amount	:S\$	180.00
Check Items (Estimated)	:S\$	6,650.00
Total	:S\$	6,830.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	17,023.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,977.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING PARTS PRICES FROM REPAIRER.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.