

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Steve Lim

Date: 04 Aug 2023

Preliminary Advice

Vehicle No	: SNL2771R	Accident Date	: 27/07/2023
Make	: SUZUKI SWIFT	Policy No.	: SP2006541754
Assignment Date	: 03/08/2023	Excess	: S\$2,000.00
Date of Inspection	: 03/08/2023	Est. Duration of Repair	: 5
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,748.00
Revised Amount	:S\$	5,520.00
Check Items (Estimated)	:S\$	1,023.00
Total	:S\$	6,543.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	94,676.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,324.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please be informed that vehicle is brand new. No maintainance done yet. Surveyor unable to test the steering system due to damage to its undercarriage. The brakes was tested and found to be in order. Tyres condition is serviceable with 9mm tread depth.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.