

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0199/2023
DATE : 01-AUG-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
9 ROBINSON ROAD
#09-01 SINGAPORE
S(068897)
TEL : 6395 8973
FAX :

OWNER'S NAME : ONG KIM CHOON
ADDRESS : APT BLK 860 JURONG WEST STREET 81
#03-592
S(640860)
TELEPHONE NO : 9879 3889

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7230026748 AIG
VEHICLE NO : SNK416K
MODEL CODE : GT7EKBL
MODEL/YEAR : IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YP51495
CHASSIS NO : JF1GT7KL5MG121587
MILEAGE : 1 KM
DATE IN : 01/08/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 01/08/2023

Print Date : 01/08/2023
Print Time : 18:25:21

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNK416K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ-GBL9593J		
2	ZZ/001	DOA:31/JUL/2023 TIME:1651 HRS LOC:JURONG WEST ST 81 BETWEEN BLK 863 & BLK 866		
3	ZZ/002	REPLACE REAR BUMPER & RHS QUARTER PANEL	3500.00	
4	ZZ/003	RESPRAY REAR BUMPER & RHS QUARTER PANEL	3000.00	
5	ZZ/004	TRANSFER/BALANCE TYRE/RIM	50.00	
6	ZZ/005	4 WHEEL ALIGNMENT	220.00	
7	ZZ/006	REMOVE & INSTALL RHS QUARTER GLASS	180.00	
8	ZZ/007	SUPPLY & INSTALL RHS QUARTER GLASS SOLAR FILM	145.00	
9	ZZ/008	REMOVE & REFIX FUEL TANK TO FACILITATE REPAIR	200.00	
10	ZZ/009	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	
11	ZZ/011	TO CONDUCT REAR RHS ANTI-RUST COATING	580.00	
12	ZZ/012	ACCESSORIES-PAINT PROTECTION FILM (TBA)		
13	ZZ/013	ACCESORIES-SOUND PROOFING (TBA)		
14	ZZ/014	FAULT DIAGNOSTIC (RESET)	280.00	
15	ZZ/015	SUNDRIES	100.00	
16	ZZ/10	TO CONDUCT REAR LIGHTING TEST	50.00	
		TOTAL LABOUR CHARGES	8455.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNK416K

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	VALVE TPMS ASSY	28103FL010			168.30	
2	DISC WHEEL AL 17 17	28111FL280			1500.00	
3	PNL SD OUT QTR RP5RH	51439FL1009P			973.10	
4	BUMPER FACE R 5D FHI	57704FL230			610.50	
5	BRKT SD R 5D RH	57707FL361			24.10	
6	BRKT SD R 5D LH	57707FL371			24.10	
7	BRKT LWR R	57707FL510			26.00	
8	COVER HOOK R 5D FHI	57731FL550NN			9.30	
9	WDW GL ASSY R QTR RH	65209FL042			865.80	
10	DAM RUBBER	65245FL010			10.20	
11	SEAL A	65277FL000			4.30	
12	CLIP BMPR *12PCS	909140007			28.80	
13	CLIP *2PCS	909140062			6.00	
14	CLIP *2PCS (REAR MUD GUARD CLIP)	909140065			3.80	
SUB TOTAL			0.00	0.00	4254.30	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	4254.30	0.00
OVERALL TOTAL			4254.30			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNK416K

TOTAL LABOUR CHARGES	8455.00
TOTAL SPARE PARTS CHARGES	4254.30

GRAND TOTAL	12709.30 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.