



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 1
DOCUMENT NO.: 967
DOCUMENT DATE: 02/08/2023
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 60638
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6250 7388
MODEL: MX5 AT BLACK INT
CHASSIS NO.: JM6ND2E7A00100160
ENGINE NO.: PE30831273
REG NO.: SLJ2217J
REGN DATE: 30/11/2016

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	LONPAC TP CLAIM	0.00	0.00		0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER, REAR INFORCEMENT. AND ALL ACCIDENT AFFECTED AREA.	3,300.00	1.00		3,300.00	S
SUB	TO RESPARY REAR BUMPER.	1,260.00	1.00		1,260.00	S
SUB	TO TRANSFER REVERSE SENSORS.	330.00	1.00		330.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.	250.00	1.00		250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	250.00	1.00		250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	300.00	1.00		300.00	S
SUB	SUNDRIES.	50.00	1.00		50.00	S
NAY5-50-22XCB	REAR BUMPER ND	1.00	1,223.07	STOCK	1,223.07	S
B45A-56-146A	FASTENER	4.00	2.36	STOCK	9.44	S
BHN1-50-0Z1A	GROMMET,SCREW	2.00	2.36	STOCK	4.72	S
BN8F-50-355	RIVET	4.00	4.64	STOCK	18.56	S
N243-50-2H1B	RETAINER(R),REAR BUM ND	1.00	34.06	STOCK	34.06	S
N243-50-2J1B	RETAINER(L),REAR BUM ND	1.00	34.06	STOCK	34.06	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64	STOCK	4.64	S
NA1J-50-260	REINF.,REAR BUMPER ND	1.00	763.21		763.21	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 12 Sungei Kadut Ave Singapore 729648
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620

ZOOM-ZOOM



QUOTATION

CODE: L0002
 CUSTOMER: LONPAC INSURANCE BHD
 ADDRESS: 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

PAGE NO.: 2
 DOCUMENT NO.: 967
 DOCUMENT DATE: 02/08/2023
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV:
 CSP/OP CODE: Lee Yao Sheng
 DEPT: I
 WIP NO.: 60638
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

CONTACT NO.: 6250 7388
 MODEL: MX5 AT BLACK INT
 CHASSIS NO.: JM6ND2E7A00100160
 ENGINE NO.: PE30831273
 REG NO.: SLJ2217J
 REGN DATE: 30/11/2016

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
N243-51-067	BRACKET'A' ND	1.00	2.36	STOCK	2.36	S
N243-51-077	BRACKET'B' ND	1.00	2.36	STOCK	2.36	S
N243-50-231	BUMPER(R),REAR ND	1.00	25.96	STOCK	25.96	S
N243-50-241	BUMPER(L),REAR ND	1.00	25.96	STOCK	25.96	S
N243-50-321B	BRACKET(R),REAR BUMP ND	1.00	30.85	STOCK	30.85	S
N243-50-331B	BRACKET(L),REAR BUMP ND	1.00	30.85	*NO STOCK	30.85	S
N243-50-151A	BRACKET(R),FRT BUMPE ND	1.00	31.36	STOCK	31.36	S
N243-50-161A	BRACKET(L),FRT BUMPE ND	1.00	31.36	STOCK	31.36	S
FB01-50-133C	NUT,CLIP	2.00	3.29	STOCK	6.58	S
DA6T-67-UC1 6	SENSOR,ULTRASONIC DJ/DK/ND	4.00	159.14	STOCK	636.56	S
NB0D-67-290	CORD,SHORT ND	1.00	395.89	STOCK	395.89	S
N243-50-2G2	SEAL,RUBBER ND	2.00	9.28	STOCK	18.56	S
N243-51-771	ORNAMENT ND	1.00	71.65	STOCK	71.65	S
NA1P-51-721	ORNAMENT,CAR NAME-RE ND	1.00	59.76	STOCK	59.76	S
NC10-50-2G2	SEAL,RUBBER ND	4.00	1.86	STOCK	7.44	S
G043-62-864A	TAPE,PROTECTOR	2.00	2.95	*NO STOCK	5.90	S
N243-51-150G	LAMP(R),RR COMB ND	1.00	944.68	*NO STOCK	944.68	S
N243-51-160G	LAMP(L),RR COMB ND	1.00	944.68	STOCK	944.68	S
BHN1-50-0Z1A	GROMMET,SCREW	2.00	2.36	STOCK	4.72	S
KD53-51-146B	FASTENER	2.00	3.71		7.42	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 12 Sungei Kadut Ave Singapore 729648

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620

zoom-zoom

