

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Billing To: Ong Shi Hao Sebastian
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP22070045

Date: 18 NOV 2022

Vehicle no: FY9196G

Model : HONDA CB400SF

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 18 JUL 2022 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 600.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 600.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP22070045

Date: 18 NOV 2022

Ong Shi Hao Sebastian
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY ACCIDENT OCCURED ON 15 JUL 2022

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 18 JUL 2022
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
FY9196G

1. VEHICLE PARTICULARS

Registration No : FY9196G
Model : HONDA CB400SF
Year / Capacity : FEB 2005 / 399 cc
Chassis No : JH2NC39984M020003

Engine No : NC23E2063896
Mileage : n.a km
Colour : Multi colour

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	80/90/R17	Bridgestone	9.00 mm	Sport
REAR O/S :	80/90/R17	Bridgestone	9.00 mm	Sport
FRONT N/S :				
REAR N/S :				

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : FY9196G

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Exhaust mainfold	bent	\$ 180.00	\$ 180.00
1 pc	Exhaust pipe	bent	\$ 1,280.00	\$ 1,280.00
2 pcs	Rear signal light	cracked	\$ 90.00	\$ 90.00
1 pc	Rear Swing arm assy	bent/distorted	\$ 828.00	\$ 828.00
1 set	Rear footrest bracket	necessary	\$ 318.60	\$ 318.60
1 pc	Rear footrest	bent	\$ 90.00	\$ 90.00
1 pc	Rear tail lamp w cover	cracked	\$ 222.00	\$ 222.00
1 pc	Rear side fairing cover	deformed	\$ 450.00	\$ 450.00
1 pc	Brake lever	grazed/deformed	\$ 85.00	\$ 85.00
Parts Sub-Total			\$ 3,543.60	\$ 3,543.60
Discount 10.00%			\$ 354.36	\$ 354.36
			\$ 3,189.24	\$ 3,189.24

Vehicle Number : FY9196G


QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 pc	Number plate	Bent	\$ 75.00	\$ 75.00
2 blts	Fork oil	Necessary	\$ 30.00	\$ 30.00
2 blts	Brake oil	Necessary	\$ 30.00	\$ 30.00
1 pc	Rim	damaged	\$ 350.00	\$ 350.00
1 pc	Tyre	damaged	\$ 150.00	\$ 150.00
1 pc	Side engine bar	distorted	\$ 280.00	\$ 280.00
1 pc	Handle bar	bent	\$ 225.00	\$ 225.00
1 set	Handle grip	bent	\$ 100.00	\$ 100.00
Special Nett Sub-Total			\$ 1,240.00	\$ 1,240.00
Spare Parts Total			\$ 4,429.24	\$ 4,429.24

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 4,429.24	\$ 4,429.24
1	Towing charges	\$ 150.00	\$ 150.00
2	Labour charges	\$ 1,400.00	\$ 1,200.00
3	To putty, apply primer & spray-paint the affected areas.	\$ 1,200.00	\$ 1,000.00
4	To apply rust-proofing on repaired/replaced panels.	\$ 120.00	\$ 100.00
	Total	\$ 7,299.24	\$ 6,879.24

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 5,500.00


Fong Kok Heng
Qualified Appraiser



ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J

Woodlands Road

Singapore 677978

Tel: 6760 6271

Ong Shi Hao, Sebastian

c/o M/s Eng Soon Painting Services

Block 4 Yew Tee Ind Est 393-

Woodlands Road

Singapore 677969

Date: 18 November 2022

Dear Sir,

Date of accident : 15 July 2022

Final repair bill to: FY 9196 G

To Supply,

Repairs recommended

By the surveyor \$5,500.00

Total \$5,500.00

Dollars: FIVE THOUSAND FIVE HUNDRED ONLY