



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TOH HONG KENG JAMES (ZHUO FENGQING JAMES) 15 WOODLANDS DRIVE 72 #14-41 SINGAPORE 738096  Contact No Mobile: 96252080	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQ)
	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600417
	Engine No	4J11AB9066
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/12/2021/ 11:30	BLC	442 / CocoLu	18623

  

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET, FRT BUMPER, FRT FENDER LH, REPAIR FRT SUPPORT PANEL FRT DOOR LH, FRT FENDER RH				2250.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH FRT DOOR LH, FRT SUPPORT PANEL				2100.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
A 54900099 CHECK WIRING & ELECTRICAL SYTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
M FACE,FR BUMPER	1.00	851.00	00.00	851.00
M GARNISH,FR BUMPER,LH	1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER,RH	1.00	48.00	00.00	48.00
M EXTENSION,FR BUMPER	1.00	517.00	00.00	517.00
M BRACKET,FR BUMPER SIDE,LH	1.00	18.00	00.00	18.00
M BRACKET,FR BUMPER SIDE,RH	1.00	18.00	00.00	18.00
M BRKT,FR BUMPER SIDE,LWR LH	1.00	6.00	00.00	6.00
M BRKT,FR BUMPER SIDE,LWR RH	1.00	6.00	00.00	6.00
M GARNISH,FR LICENSE PLATE	1.00	23.00	00.00	23.00
M GARNISH,FR BUMPER SIDE	1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE	1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE	1.00	220.00	00.00	220.00
M GARNISH,FR BUMPER SIDE	1.00	220.00	00.00	220.00
M GARNISH,FR BUMPER SIDE	1.00	112.00	00.00	112.00
M GARNISH,FR BUMPER SIDE	1.00	112.00	00.00	112.00
M GARNISH,FR BUMPER SIDE	1.00	112.00	00.00	112.00
M COVER,FR BUMPER	1.00	361.00	00.00	361.00
M MOULDING,FR BUMPER,LH	1.00	116.00	00.00	116.00

Confirm &amp; accepted by

\_\_\_\_\_  
 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TOH HONG KENG JAMES (ZHUO FENGQING JAMES) 15 WOODLANDS DRIVE 72 #14-41 SINGAPORE 738096  Contact No Mobile: 96252080	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQ)
	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600417
	Engine No	4J11AB9066
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/12/2021/ 11:30	BLC	442 / CocoLu	18623			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	COVER,HEADLAMP SUPT PANEL	1.00	50.00	00.00	50.00			
M	COVER,FR BUMPER	1.00	25.00	00.00	25.00			
M	GRILLE ASSY,RADIATOR	1.00	550.00	00.00	550.00			
M	BRACKET,RADIATOR GRILLE,RH	1.00	17.00	00.00	17.00			
M	BRACKET,RADIATOR GRILLE,LH	1.00	13.00	00.00	13.00			
M	REINFORCEMENT,FR BUMPER	1.00	493.00	00.00	493.00			
M	BAR,FR BUMPER GUARD	1.00	130.00	00.00	130.00			
M	REINFORCEMENT,FR BUMPER	1.00	135.00	00.00	135.00			
M	REINFORCEMENT,FR BMPR SIDE	1.00	22.00	00.00	22.00			
M	REINF,FR BUMPER SIDE,RH	1.00	69.00	00.00	69.00			
M	REINF,FR BUMPER SIDE,LH	1.00	60.00	00.00	60.00			
M	HOOD	1.00	980.00	00.00	980.00			
M	INSULATOR,HOOD	1.00	133.00	00.00	133.00			
M	WEATHERSTRIP,HOOD	1.00	40.00	00.00	40.00			
M	WEATHERSTRIP,HOOD	1.00	41.00	00.00	41.00			
M	LATCH,HOOD	1.00	76.00	00.00	76.00			
M	FENDER,FR LH	1.00	622.00	00.00	622.00			
M	SHIELD,FR WHEELHOUSE,LH	1.00	164.00	00.00	164.00			
M	HEADLAMP ASSY,LH	1.00	1948.00	00.00	1948.00			
M	HEADLAMP ASSY,RH	1.00	1948.00	00.00	1948.00			
M	LAMP ASSY,FOG,FR LH	1.00	350.00	00.00	350.00			
M	LAMP ASSY,FOG,FR RH	1.00	348.00	00.00	348.00			

# Estimate

Confirm &amp; accepted by

	<b>Nett</b>	<b>15,596.00</b>
7% GST on	<b>15596.00</b>	<b>1091.72</b>
<b>Total Payable</b>		<b>16,687.72</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.