ASS. REC. BY: | REF: CS|MSG18006378/Uqd3 | Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Meinmen Elaine Ngu of MSIG Date/Time: 06/04/18

Estimated Cost: Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 5082Z Insured: SDY2210T

at Workshop m/s: Ban Huck Hin Tel: 62816520

of: No. 6 Defu Lane 4

Policy No: 27320685SMP Claim No: 5546 6

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 02/04/18

CA / REV / REP. / REV 24 HRS (up)

R.O.D. Endorsement:

Date/Time: 11:49am 06/4/18 Person Contacted: Khalid Vehicle (IN) / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBK 5082Z - X
	SDY 2210T - X
10/4/18	30p voiced to Elaine Ngu via telemen.

(08/11/13) wef

ASS. REC. BY: Marcus

REF: MSW/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK5082Z

at Workshop m/s BHH

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: FBK5082Z Yr Regn: 10 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Yamaha YBR125 c.c 124

Colour orange A/C: Insured / Std / NI / NA

Sp.Reading 30038 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LBPRE10100005577

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18

R: 90-90-18 IRC

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	2/4/18	D.O.I	6/4/18

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear & N/C, O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/4/18	Confirmed final fig @ $541.70 with Raymond. (Prev $668.30, 55%)
	CDR Seen 24/04/2013

RECEIVED 24 APR 2018

Date/Time. File Pass to? 1) 24/4 [illegible]

Date/Time. File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : MEP-TP

Lump Sum / I.B.I: ($ 541.70)

Survey Fee:

Transportation: $ + RS SI

Photos

Others

TOTAL

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Ref : CS/MSG18006378/Uqd3

Date : 06-04-2018

Code : MSG

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SDY 2210T	Veh. Inspected	FBK 5082Z
	Policy No.	27320685SMP	Coverage ($)	0.00
	Claim No.	554646	Excess ($)	0.00
	Assign From	MERIMEN (ELAINE NGU)	Assign Date	06/04/2018

2.	Vehicle Particulars & Condition			
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4.	Description of Damages

5.	General Information			
	Accident Date	02/04/2018	Inspection Date	06/04/2018
	Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Appr'ed	Status
Main	02 Apr 2018		06 Apr 2018 10:55 Assign				**New Assignment** Cancel Case

Main | **Reference** | **Claim Details** | **Documents** | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**K,ASOKAN**, ID: S1606578A		
Main Claimant:	**MAGIX FOOD ENTERPRISE**, Co. Reg. No.: 53065880A		
Vehicle Reg. No.:	**FBK5082Z**	Date of Loss:	02/04/2018 11:00 - :59 [**29** Months and **30** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 554646	Policy/Cover Note No.:	27320685SMP (Comprehensive) Coverage: 10/05/2017 - 09/05/2018
Vehicle Reg. No. (Insured):	**SDY2210T**	Policy No. (Claimant):	
		Excess:	S$750.00
Repairer:	**Ban Hock Hin Co. Pte Ltd (HQ)** No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Elaine Ngu Siau Mei** - 6594 2540]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 07/04/2018]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBK5082Z
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	YBR125
Chassis No. :	LBPRE101000055577
Propellant :	Petrol
Engine No. :	E3F5E040654
Engine Capacity :	124 cc
Maximum Power Output :	-
Maximum Laden Weight :	320 kg
Unladen Weight :	114 kg
Year Of Manufacture :	2015
Original Registration Date :	03 Oct 2015
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	$6,112.00
COE Expiry Date :	02 Oct 2025
Road Tax Expiry Date :	02 Oct 2018
Inspection Due Date :	02 Oct 2018
Intended Transfer Date :	06 Apr 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			**25.00**

You may print this page for reference.

OK Print

MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg No. 200612224)
4 Shenton Way, # 21-01, SGX Centre2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
The Motor Vehicles (Third Party Risks) Rules, 1959 (Federation of Malaysia)
Motor Vehicles (Third Party Risks and Compensation) Act (CAP. 189 of the Revised Edition) (Republic of Singapore)
The Motor Vehicles (Third Party Risks and Compensation) Rules, 1996 Edition (Republic of Singapore)
Or any Amendment, Act or Acts passed in substitution thereof.

RIDICATE NO : MSO/VAT/17-986209-WTT A0633-001/W0003

INSURED : TPL

CESS : NIL

Index mark and Registration Number of Vehicle 53665880A FBX5802I

YAMAHA 124 c.c.

Name of Policyholder MAGIE FOOD ENTERPRISE

Effective date of the Commencement of Insurance for the purposes of the Act 0001AM 07/11/2017

Date of Expiry of Insurance 06/11/2018

Persons or Classes of Persons entitled to drive

1. Any person who is driving on the Policyholder's order or with their permission,

ovided that the person driving is permitted in accordance with the licensing other laws or regulations to drive the Motor Vehicle or has been so permitted d is not disqualified by order of a Court of Law or by reason of any enactment regulation in that behalf from driving the Motor Vehicle. And provided further that e Motor Vehicle is registered and licensed under the Road Traffic Act and its gistration and licensing under the Road Traffic Act has not been cancelled at the ne of the accident loss or damage.

Limitation as to Use

Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

The Policy does not cover

. Use for hire or reward.

:. Use for racing,pace-making,reliability trial or speed-testing.

. Use for any purpose in connection with the Motor Trade.

Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

VE HEREBY CERTIFY that the Policy to which this Certificate relates is ued in accordance with the provisions of the Motor Vehicles (Third-Party Risks d Compensation) Act (Chapter 189) and the Road Transport Act, 87 (Malaysia).

WTT INSURANCE AGENCIES PTE LTD

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Apr 2018

Preliminary Advice

Insured Vehicle No	: SDY2210T
TP Vehicle No	: FBK5082Z
Make	: YAMAHA YBR125
Date of Inspection	: 06/04/2018
Inspection At	: BAN HOCK HIN CO. PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410

Accident Date	: 02/04/2018
Assignment Date	: 06/04/2018
Est. Duration of Repair	: 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion & n/s, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	1,210.00
Revised Amount	:S$	551.00
Check Items (Estimated)	:S$	1.50
Total	:S$	552.50
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5880A
Vehicle Details	
Vehicle No.:	FBK5082Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	E3F5E040654
Chassis No.:	LBPRE101000055577
Maximum Power Output:	-
Open Market Value:	$1,941.00
Original Registration Date:	03 Oct 2015
First Registration Date:	03 Oct 2015
Transfer Count:	1
Actual ARF Paid:	$292.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	$6,112.00
COE Rebate Amount:	$4,577.00
Total Rebate Amount:	**$4,577.00**

The information contained herein is correct as at 06 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/04/2018 15:48
Date Of Accident	02/04/2018 11:55
Exact Location Of Accident	206A CHUA CU KANG AVE 1(OUTSIDE RITE PIZZA)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBK5082Z
Insured/Policyholder	
Name Of Registered Owner	MAGIX FOOD ENTERPRISE
Co Reg No	53065880A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96904979
Vehicle Particulars	
Manufacturer	YAMAHA
Model	YBR125
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	MSD/VMT/17-986209-WTT
Cover Note Number	
Driver	
Name of Driver	ANDIAN BIN ZAINAL
NRIC No	S9022381Z
Date Of Birth	22/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	19/06/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96904979
Fax Number	
Contact Number	
EMail Address	YEOQIN@HOTMAIL.COM

Address	BLK 119 BUKIT BATOK WEST AVENEU 6 #02-254 SINGAPORE 650119
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

The bike FBK5082Z was stationary infront of the shop,suddenly the other party SDY2210T reversed back and bang onto the bike.No injuries involved

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDY2210T
Vehicle Make/Model/Colour	B.M.W./520I
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	K ASOKAN
NRIC/Passport Number	S1606578A
Contact Number	94880635
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available at/read.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have their vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MAI
REPORTING OFFICER
MUHAMMAD SUMARDI
MOHD AFFANDI

Policyholder's Signature / Date & Time | Driver's Signature (if driver is not the policyholder) / Date & Time | Witnessed by Reporting Car Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

The bike FBK5082Z was stationary infront of the shop,suddenly the other party SDY2210T reversed back and bang onto the bike.No injuries involved

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER - MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

2 April 2018 3:07 pm

Date/Time:

2 April 2018 3:07 pm

BAN HOCK HIN Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : **32503**

Customer :

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

not Actual
LHL
Take photo After
repair
3 day.
6/4/18

DATE : 03/04/2018
CLAIM NO. : 11126
POLICY NO. : MSD/VMT/17-986209-WT
FROM : RAYMOND

VEHICLE NO. : FBK5082Z
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price		Amount	
1	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712	REPLACE	1.00	$30.00	Set	30.00	—
2	CRASH BAR P/N: 35878	REPLACE	1.00	$195.00	20 n/c	195.00	X
3	DAMPER FOOTREST P/N: 52712	REPLACE	1.00	$2.50	11	2.50	X
4	FOOTREST REAR ASSY LH P/N: 25348	REPLACE	1.00	$15.00	11	15.00	X
5	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	$14.00	Tocn	14.00	—
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	4.00	$35.00	120	140.00	
7	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	$63.00	11	63.00	X
8	LEVER BRAKE P/N: 26343	REPLACE	1.00	$19.00	Set	19.00	—
9	LEVER CLUTCH P/N: 26342	REPLACE	1.00	$12.00	11	12.00	X
10	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	$200.00	11	200.00	X
11	MIRROR LH P/N: 26137	REPLACE	1.00	$15.00	cn/sy	15.00	—
12	MIRROR RH P/N: 26503	REPLACE	1.00	$15.00	scn	15.00	—
13	PLATE P/N: 52713	REPLACE	1.00	$1.50	11	1.50	X

S/N	Description	Action	Qty	Unit Price	1/C	Amount
14	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	$56.00	CAT	56.00 X
15	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	$14.00	11	14.00 X
16	SPRAY PAINT ON FIBER BOX	Spray	1.00	$210.00	180	210.00
17	SPRAY PAINT ON FRONT FENDER	Spray	1.00	$50.00	11	50.00 X
18	STICKER (HALAL) 9CM P/N: 29313	REPLACE	2.00	$2.50	11	5.00
19	STICKER (RITE PIZZA) BOX REAR 17" X 23" P/N: 29117	REPLACE	1.00	$50.00	11	50.00
20	STICKER (RITE PIZZA) FUEL TANK P/N: 29118	REPLACE	2.00	$10.00	11	20.00
21	STICKER (RITE PIZZA) TEL NO:68993838 - SMALL P/N: 29195	REPLACE	3.00	$16.00	11	48.00
22	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	$35.00		35.00

SUB TOTAL	$1,210.00
GST @ 7 %	$84.70
GRAND TOTAL	**$1,294.70**

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-93

BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32503 - Rev. 1

Customer :

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

DATE : 03/04/2018
CLAIM NO. : 11126
POLICY NO. : MSD/VMT/17-986209-WT

FROM : RAYMOND

VEHICLE NO. : FBK5082Z
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712	REPLACE	1.00	$30.00 Disc %: 10.00	27.00
2	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	$14.00 Disc %: 10.00	12.60
3	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	4.00	$30.00	120.00
4	LEVER BRAKE P/N: 26343	REPLACE	1.00	$19.00 Disc %: 10.00	17.10
5	MIRROR LH P/N: 26137	REPLACE	1.00	$15.00 Disc %: 10.00	13.50
6	MIRROR RH P/N: 26503	REPLACE	1.00	$15.00 Disc %: 10.00	13.50
7	SPRAY PAINT ON FIBER BOX	Spray	1.00	$180.00	180.00
8	STICKER (HALAL) 9CM P/N: 29313	REPLACE	2.00	$2.50	5.00
9	STICKER (RITE PIZZA) BOX REAR 17" X 23" P/N: 29117	REPLACE	1.00	$50.00	50.00
10	STICKER (RITE PIZZA) FUEL TANK P/N: 29118	REPLACE	2.00	$10.00	20.00
11	STICKER (RITE PIZZA) TEL NO:68993838 - SMALL P/N: 29195	REPLACE	3.00	$16.00	48.00
12	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	$35.00	35.00

SUB TOTAL	$541.70
GST @ 7 %	$37.92

S/N	Description	Action	Qty	Unit Price	Amount
		GRAND TOTAL			$579.62

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

BAN HOCK HIN CO PTE LTD

RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018		24 Apr 2018 11:45 Edit Adj Rpt	**S$541.70** Edit Estimates	**S$541.70** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**K,ASOKAN**, ID: S1606578A		
Main Claimant:	**MAGIX FOOD ENTERPRISE**, Co. Reg. No.: 53065880A		
Vehicle Reg. No.:	**FBK5082Z**	Date of Loss:	02/04/2018 11:00 - :59 [**29** Months and **30** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 554656	Policy/Cover Note No.:	27320685SMP (Comprehensive) Coverage: 10/05/2017 - 09/05/2018
Vehicle Reg. No. (Insured):	**SDY2210T**	Policy No. (Claimant):	
		Excess:	S$750.00
Repairer:	**Ban Hock Hin Co. Pte Ltd (HQ)** No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Elaine Ngu Siau Mei** - 6594 2540]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [**Imm.Advice** due 25/04/2018]		
Driver/Custodian (Insured):	K,ASOKAN (), NRIC: S1606578A		
Adj Asg. Remarks:	ALREADY SURVEY		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBK5082Z (554656)**
[SDY2210T]
TP
MAGIX FOOD ENTERPRISE
Apr 2 2018 11:00AM
[K,ASOKAN]
Ban Hock Hin Co. Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Letters/Correspondences — 1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/04/18 11:26	**Letter to OI Informing TPD**	1	Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/04/18 11:52	**Chassis Number**	1	Load JPG	☑
2	24/04/18 11:52	**Odometer Reading**	1	Load JPG	☑
3	24/04/18 11:52	**General View**	1	Load JPG	☑
4	24/04/18 11:52	**General View**	1	Load JPG	☑
5	24/04/18 11:52	**General View**	1	Load JPG	☑
6	24/04/18 11:52	**General View**	1	Load JPG	☑
7	24/04/18 11:52	**General View**	1	Load JPG	☑
8	24/04/18 11:52	**General View**	1	Load JPG	☑
9	24/04/18 11:52	**General View**	1	Load JPG	☑
10	24/04/18 11:52	**General View**	1	Load JPG	☑
11	24/04/18 11:52	**General View**	1	Load JPG	☑
12	24/04/18 11:52	**General View**	1	Load JPG	☑
13	24/04/18 11:52	**General View**	1	Load JPG	☑
14	24/04/18 11:52	**General View**	1	Load JPG	☑
15	24/04/18 11:52	**General View**	1	Load JPG	☑
16	24/04/18 11:52	**General View**	1	Load JPG	☑
17	24/04/18 11:52	**General View**	1	Load JPG	☑
18	24/04/18 11:52	**General View**	1	Load JPG	☑
19	24/04/18 11:52	**General View**	1	Load JPG	☑
20	24/04/18 11:52	**General View**	1	Load JPG	☑
21	24/04/18 11:52	**General View**	1	Load JPG	☑
22	24/04/18 11:52	**General View**	1	Load JPG	☑
23	24/04/18 11:52	**General View**	1	Load JPG	☑
24	24/04/18 11:52	**General View**	1	Load JPG	☑
25	24/04/18 11:52	**General View**	1	Load JPG	☑
26	24/04/18 11:52	**General View**	1	Load JPG	☑
27	24/04/18 11:52	**General View**	1	Load JPG	☑
28	24/04/18 11:52	**General View**	1	Load JPG	☑
29	24/04/18 11:52	**General View**	1	Load JPG	☑
30	24/04/18 11:52	**General View**	1	Load JPG	☑
31	24/04/18 11:52	**General View**	1	Load JPG	☑
32	24/04/18 11:52	**General View**	1	Load JPG	☑
33	24/04/18 11:52	**General View**	1	Load JPG	☑
34	24/04/18 11:52	**General View**	1	Load JPG	

Letters/Correspondences			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
					☑
35	24/04/18 11:52	General View		Load JPG	☑
36	24/04/18 11:52	General View		Load JPG	☑
37	24/04/18 11:52	General View		Load JPG	☑
38	24/04/18 11:52	General View		Load JPG	☑
39	24/04/18 11:52	General View		Load JPG	☑
40	24/04/18 11:53	Reinspection Photo		Load JPG	☑
41	24/04/18 11:53	Reinspection Photo		Load JPG	☑
42	24/04/18 11:53	Reinspection Photo		Load JPG	☑
43	24/04/18 11:53	Reinspection Photo		Load JPG	☑
44	24/04/18 11:53	Reinspection Photo		Load JPG	☑
45	24/04/18 11:53	Reinspection Photo		Load JPG	☑
46	24/04/18 11:53	Reinspection Photo		Load JPG	☑
47	24/04/18 11:53	Reinspection Photo		Load JPG	☑
48	24/04/18 11:53	Reinspection Photo		Load JPG	☑
49	24/04/18 11:53	Reinspection Photo		Load JPG	☑
50	24/04/18 11:53	Reinspection Photo		Load JPG	☑
51	24/04/18 11:53	Reinspection Photo		Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/04/18 11:06	OUTSTANDING PREMIUM - SDY2210T.pdf		Load PDF	
2	20/04/18 11:07	FACE SHEET & POLICY - SDY2210T.pdf		Load PDF	
3	20/04/18 11:07	TPD FBK 5082Z EST & EST & PRI & GIA REPORT.pdf		Load PDF	
4	20/04/18 11:07	PRI- FBK5082Z.pdf		Load PDF	
5	20/04/18 11:07	Full page photo 51- FBK5082Z.pdf		Load PDF	
6	20/04/18 11:07	Full page photo 50- FBK5082Z.pdf		Load PDF	
7	20/04/18 11:07	Full page photo 49 -FBK5082Z.pdf		Load PDF	
8	20/04/18 11:08	Full page photo 48- FBK5082Z.pdf		Load PDF	
9	20/04/18 11:08	Full page photo 47- FBK5082Z.pdf		Load PDF	
10	20/04/18 11:08	Full page photo 46- FBK5082Z.pdf		Load PDF	
11	20/04/18 11:08	Full page photo 45- FBK5082Z.pdf		Load PDF	
12	20/04/18 11:08	Full page photo 44- FBK5082Z.pdf		Load PDF	
13	20/04/18 11:08	Full page photo 43- FBK5082Z.pdf		Load PDF	
14	20/04/18 11:08	Full page photo 42- FBK5082Z.pdf		Load PDF	
15	20/04/18 11:08	Full page photo 41- FBK5082Z.pdf		Load PDF	
16	20/04/18 11:08	Full page photo 40- FBK5082Z.pdf		Load PDF	
17	20/04/18 11:09	Full page photo 39- FBK5082Z.pdf		Load PDF	
18	20/04/18 11:09	Full page photo 38- FBK5082Z.pdf		Load PDF	
19	20/04/18 11:09	Full page photo 37 FBK5082Z.pdf		Load PDF	
20	20/04/18 11:09	Full page photo 36- FBK5082Z.pdf		Load PDF	
21	20/04/18 11:09	Full page photo 35- FBK5082Z.pdf		Load PDF	
22	20/04/18 11:09	Full page photo 34- FBK5082Z.pdf		Load PDF	
23	20/04/18 11:09	Full page photo 33- FBK5082Z.pdf		Load PDF	
24	20/04/18 11:09	Full page photo 32- FBK5082Z.pdf		Load PDF	
25	20/04/18 11:09	Full page photo 31- FBK5082Z.pdf		Load PDF	
26	20/04/18 11:09	Full page photo 30- FBK5082Z.pdf		Load PDF	
27	20/04/18 11:10	Full page photo 29- FBK5082Z.pdf		Load PDF	
28	20/04/18 11:10	Full page photo 28- FBK5082Z.pdf		Load PDF	
29	20/04/18 11:10	Full page photo 27- FBK5082Z.pdf		Load PDF	
30	20/04/18 11:10	Full page photo 26- FBK5082Z.pdf		Load PDF	
31	20/04/18 11:10	Full page photo 25- FBK5082Z.pdf		Load PDF	
32	20/04/18 11:10	Full page photo 24- FBK5082Z.pdf		Load PDF	
33	20/04/18 11:10	Full page photo 23- FBK5082Z.pdf		Load PDF	
34	20/04/18 11:10	Full page photo 22- FBK5082Z.pdf		Load PDF	
35	20/04/18 11:11	Full page photo 21- FBK5082Z.pdf		Load PDF	
36	20/04/18 11:11	Full page photo 20- FBK5082Z.pdf		Load PDF	

Letters/Correspondences			1 per page		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
37	20/04/18 11:11	Full page photo 19- FBK5082Z.pdf		Load PDF	
38	20/04/18 11:11	Full page photo 18- FBK5082Z.pdf		Load PDF	
39	20/04/18 11:11	Full page photo 17- FBK5082Z.pdf		Load PDF	
40	20/04/18 11:11	Full page photo 16- FBK5082Z.pdf		Load PDF	
41	20/04/18 11:12	Full page photo 15- FBK5082Z.pdf		Load PDF	
42	20/04/18 11:12	Full page photo 14- FBK5082Z.pdf		Load PDF	
43	20/04/18 11:12	Full page photo 13- FBK5082Z.pdf		Load PDF	
44	20/04/18 11:12	Full page photo 12- FBK5082Z.pdf		Load PDF	
45	20/04/18 11:12	Full page photo 11- FBK5082Z.pdf		Load PDF	
46	20/04/18 11:12	Full page photo 10- FBK5082Z.pdf		Load PDF	
47	20/04/18 11:12	Full page photo 9- FBK5082Z.pdf		Load PDF	
48	20/04/18 11:12	Full page photo 8- FBK5082Z.pdf		Load PDF	
49	20/04/18 11:12	Full page photo 7- FBK5082Z.pdf		Load PDF	
50	20/04/18 11:12	Full page photo 6- FBK5082Z.pdf		Load PDF	
51	20/04/18 11:12	Full page photo 5- FBK5082Z.pdf		Load PDF	
52	20/04/18 11:12	Full page photo 4- FBK5082Z.pdf		Load PDF	
53	20/04/18 11:13	Full page photo 3- FBK5082Z.pdf		Load PDF	
54	20/04/18 11:13	Full page photo 2- FBK5082Z.pdf		Load PDF	
55	20/04/18 11:13	Full page photo 1- FBK5082Z.pdf		Load PDF	
56	20/04/18 11:13	Adjuster Immediate Advice - FBK5082Z.pdf		Load PDF	
57	20/04/18 11:13	Non Reporting Letter to OI- FBK5082Z.pdf		Load PDF	
58	20/04/18 11:13	Acknowledgement Letter to TP - FBK5082Z.pdf		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/04/18 11:55	PRELIMINARY ADVICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006378/UQD3Q2
Date: 25/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27320685SMP	
Claimant Vehicle No :	FBK5082Z	**Insured Vehicle No :**	SDY2210T	
Date of Loss:	02/04/2018	Nature of Claim:	TP	Claim No: 554656

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**FBK5082Z**		
Make & Model:	YAMAHA YBR125, 124cc (M)	Engine No:	E3F5E040654
Reg. Date:	03/10/2015 (Man. Year: 2015)	Chassis No:	LBPRE101000055577
Colour:	Orange	Odometer:	30038 km
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90-90-18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	775.00	206.70	568.30	73.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	435.00	335.00	100.00	22.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**1,210.00**	**541.70**	**668.30**	**55.23**
+ GST 7.00/7.00% (S$)	84.70	37.92	46.78	55.23
Nett Amount (S$)	**1,294.70**	**579.62**	**715.08**	**55.23**

INSPECTION

Date of Assignment:	24/04/2018		
Date Inspected:	06/04/2018	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 25 Apr 2018)
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK5082Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***BRACKET IU METER (UNIVERSAL) S/STEEL**	Bent	30.00 F	*30.00 FL
2	1		***CRASH BAR (DENTED)**	Not Consistent With The Impact	195.00 F	*- FL
3	1		***DAMPER FOOTREST**	Not Necessary	2.50 F	*- FL
4	1		***FOOTREST REAR ASSY LH**	Not Necessary	15.00 F	*- FL
5	1		***GRIP HANDLE SET (GPR) F2**	Torn	14.00 F	*14.00 FL
6	1		***LAMP SIGNAL REAR LH**	Not Necessary	63.00 F	*- FL
7	1		***LEVER BRAKE**	Bent	19.00 F	*19.00 FL
8	1		***LEVER CLUTCH**	Not Necessary	12.00 F	*- FL
9	1		***METER IU (12V) NEW MODEL**	Not Necessary	200.00 F	*- FL
10	1		***MIRROR LH**	Cut / Bent	15.00 F	*15.00 FL
11	1		***MIRROR RH**	Scratched	15.00 F	*15.00 FL
12	1		***PLATE**	Not Necessary	1.50 F	*- FL
13	1		***PROTECTO EXHAUST CAP (CUT)**	Not Consistent With The Impact	56.00 F	*- FL
14	1		***RUBBER FOOTREST FRONT**	Not Necessary	14.00 F	*- FL
15	2		***STICKER (HALAL) 9CM**	Necessary	5.00 FS	*5.00 FS
16	1		***STICKER (RITE PIZZA) BOX REAR 17X23**	Necessary	50.00 FS	*50.00 FS
17	2		***STICKER (RITE PIZZA) FUEL TANK**	Necessary	20.00 FS	*20.00 FS
18	3		***STICKER (RITE PIZZA) TEL NO.68993838-SMALL**	Necessary	48.00 FS	*48.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**775.00**	**216.00**
- List Item Discount on L Items 0.00/10.00% (S$)	0.00	9.30
Total Parts (S$)	**775.00**	**206.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER)STD	New	35.00	35.00
2	SPRAY PAINT ON FIBER BOX	New	210.00	180.00
3	SPRAY PAINT ON FRONT FENDER	New	50.00	0.00
4	LABOUR-FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	New	140.00	120.00
		Gross Labour Cost (S$)	**435.00**	**335.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >